

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 300250908900
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name South Eunice Unit
2. Name of Operator Conoco Inc.	8. Well No. 48
3. Address of Operator 10 Desta Drive West, Midland, TX 79705	9. Pool name or Wildcat Eunice 7-Rivers Queen South
4. Well Location Unit Letter <u>P</u> : <u>990</u> Feet From The <u>south</u> Line and <u>330</u> Feet From The <u>east</u> Line Section <u>28</u> Township <u>22S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3475'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to clean out, open additional pay, and sand frac this well by the following procedure:

1. Tag for fill and clean out (if needed) to 3777'.
2. Perforate 7-Rivers intervals at 3614'-23', 35'-45', 68'-70', 74'-76', 78'-92 with 2 JSPF.
3. Acidize with 100 bbls 15% NEFE acid.
4. Sand frac 3614'-3745' with 50,000 # sand.
5. Perforate Queen interval at 3760'-69'.
6. Acidize Queen with 30 bbls 15% NEFE acid.
7. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Hoover TITLE Regulatory Coordinator DATE 12-12-90  
TYPE OR PRINT NAME Jerry W. Hoover TELEPHONE NO. 915-686-6548

(This space for State Use)  
APPROVED BY JERRY SEXTON  
DATE DEC 17 1990

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: