OIL GAS WELL OTHER-  2. Name of Operator  Continental Cil Company  3. Address of Operator  P. O. Box 460, Hobbs, New Mexico  7. Unit Agreement Name  8. Farm or Lease Name  State A-32  9. Well No.	V .	· · · · · · · · · · · · · · · · · · ·	
DISTRIBUTION  SANTA FE	NO. OF COPIES RECEIVED		Part C. No.
LAND OFFICE  OPERATOR  SUNDRY NOTICES AND REPORTS ON WELLS  (00 NOT USE TRIP PROBLEM FOR P	DISTRIBUTION	$\dashv$	Form C-103    JES or Supersedes Old
LAND OFFICE  OPERATOR  SUNDRY NOTICES AND REPORTS ON WELLS  (00 NOT USE TRIP PROBLEM FOR P		NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
LAND OFFICE OPERATOR  SUNDRY NOTICES AND REPORTS ON WELLS  TO NOT USE THIS FOR MANAGEMENT OF THE PROPERTY OF T	FILE	The mexico of conservation commission $f_{EB}$	211 Li Effective 44 45
Solice   Sol	U.S.G.S.	=	
SUNDRY NOTICES AND REPORTS ON WELLS  TO NOT USE THIS COUNTY OF PROPOSALS TO DELLE AND REPORTS ON WELLS  TO NOT USE THIS COUNTY OF PROPOSALS TO DELLE AND CONTROL OF THE PLOY AND ADDRESS OF THE PLOY ADDRESS OF TH	LAND OFFICE		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORWARD FOR SUNDING PARTY OF THE SERVICE AND REPORTS ON WELLS  (DO NOT USE THIS FORWARD FOR SERVICE AND REPORTS ON WELLS  (DO NOT USE THIS FORWARD FOR SERVICE AND REPORTS ON WELLS  (DO NOT USE THIS FORWARD FOR SERVICE AND REPORTS ON WELLS  (Recommend to protect the service of the s	OPERATOR		
SUNDRY NOTICES AND REPORTS ON WELLS  1. ONL SERVICE SAPERICATION OF THE PROPERTY OF THE SERVICE AND STREET FROM THE SERVICE SAPERICATION OF TH		<b>_</b>	
1. Ordinental Oil Company 2. Name of Operator Continental Oil Company 3. Address of Operator P. O. Box 460, Hobbs, New Mexico 4. Location of Well UNIT LETTER C	SUNDI	RY NOTICES AND REPORTS ON WELLS	minimizer 1
1. Ordinental Oil Company 2. Name of Operator Continental Oil Company 3. Address of Operator P. O. Box 460, Hobbs, New Mexico 4. Location of Well UNIT LETTER C	(DO NOT USE THIS FORM FOR PR USE **APPLICA	TION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS )	
State A=32  3. Address of Operator  P. O. Box 460, Hobbs, New Mexico  4. Location of Well  UNIT LETTER C	1.		7. Unit Agreement Name
Continental Oil Company  3. Address of Operator  P. O. Box 460, Hobbs, New Mexico  4. Location of Well  UNIT LETTER C	1	OTHER-	
3. Address of Operator  4. Location of Well  UNIT LETTER C	2. Name of Operator		8. Farm or Lease Name
P. O. Box 460, Hobbs, New Mexico  1. Field and Pool, or Wildedt  Jalmat Pool  THE West  LINE, SECTION 32  TOWNSHIP 22S  RANGE 36E  NMPM.  15. Elevation (Show whether DF, RT, GR, etc.)  12. County  Lea  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARIEV ABARDON  PULG AND ABRADON  PULG AND ABRADON  THE West  CHANGE PLANS  OTHER  OTHER  OTHER  OTHER  NOTICE OF Intention to plug this well was approved 3-12-62. The well was plugged in the following manner: Set 100' comment plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400',  P. OCAPICAL TOWNSHIP 20 STATES AND COMPLETED AND ABRADON  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	Continental Oil Comp	pany	State 1 22
A. Location of Well  UNIT LETTER C	3. Address of Operator		
ONIT LETTER C		, New Mexico	1
THE West LINE, SECTION 32 TOWNSHIP 22S RANGE 36E NAMPM.  15. Elevation (Show whether DF, RT, GR, etc.)  12. County  15. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULI OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100' cessent plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cessent plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	4. Location of Well		10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)  12. County  15. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	UNIT LETTER C	660 FEET FROM THE North LINE WE 1980	Jalmat Pool
The Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  Perform remedial work  Temperarily abandon  Other  Other  Other  Notice of Intention to plug this well was approved 3-12-62. The well was plugged in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.		FEET LINE AND FEET	FROM
The perform remedial work temperature of Notice of Intention to plug this well was approved 3-12-62. The well was plugged in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	THE WORT LINE, SECT	ION 32 TOWNSHIP 228 DAYES 36E	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Pilled intervals between plugs with 10 lb. mud.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Erected 4" X 4' location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Erected 4" X 4' location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.		3501' DF	Lea
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Erected 4" X 4' location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	Check	Appropriate Box To Indicate Nature of Notice Report of	
Perform Remedial work  Temporarily abandon  Pull or alter casing  Other  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Brected 4" X 4' location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	NOTICE OF 11		
TEMPORARILY ABANDON PULL OR ALTER CASING  COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JOB  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100° cement plug from 3470-3573°; shot off 5 1/2" casing at 2045° and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400°, 20 sx at 309°, and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Erected 4" X 4° location marker and restored location to original condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045° to 3,559°.			2.41 ((2.10)(1.10))
Commence Drilling opns.  Casing Test and cement Job  Other  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Brected 4" X 4' location marker and restored location to original condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERNIS CARNE
OTHER  OT	TEMPORARILY ABANDON	·—	
Notice of Intention to plug this well was approved 3-12-62. The well was plugged in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud.  Brected 4" X 4' location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	PULL OR ALTER CASING	[]	PLUG AND ABANDONMENT
Notice of Intention to plug this well was approved 3-12-62. The well was plugged in the following manner: Set 100° cement plug from 3470-3573°; shot off 5 1/2" casing at 2045° and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400°, 20 sx at 309°, and 10 sx at surface. Filled intervals between plugs with 10 lb. mud. Brected 4" X 4° location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045° to 3,559°.	<del></del>		
Notice of Intention to plug this well was approved 3-12-62. The well was plugged in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud. Erected 4" X 4' location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	OTHER		
Notice of Intention to plug this well was approved 3-12-62. The well was plugged in the following manner: Set 100' cement plug from 3470-3573'; shot off 5 1/2" casing at 2045' and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400', 20 sx at 309', and 10 sx at surface. Filled intervals between plugs with 10 lb. mud. Erected 4" X 4' location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.			
in the following manner: Set 100° cement plug from 3470-3573°; shot off 5 1/2" casing at 2045° and pulled same. Set cement plugs - 20 sx at top of 5 1/2" casing, 20 sx at 1,400°, 20 sx at 309°, and 10 sx at surface. Filled intervals between plugs with 10 lb. mud. Erected 4" X 4° location marker and restored location to eriginal condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045° to 3,559°.	<ol> <li>Describe Proposed or Completed Or work) SEE RULE 1103.</li> </ol>	perations (Clearly state all pertinent details, and give pertinent dates, incli	uding estimated date of starting any proposed
Erected 4" X 4' location marker and restored location to original condition.  Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.	in the following manner 2045' and pulled same.	r: Set 100° cement plug from 3470-3573°; show Set cement plugs - 20 sx at top of 5 1/2° co	t off 5 1/2" casing at asing, 20 sx at 1,400°,
Plugging started 5-19-62. Completed 5-28-62.  Left in hole: 5 1/2" casing from 2,045' to 3,559'.			
Left in hole: 5 1/2" casing from 2,045' to 3,559'.			
Left in hole: 5 1/2" casing from 2,045' to 3,559'.	Plugging star	rted 5-19-62. Completed 5-28-62.	
		•	
10 3/4" casing from surface to 309'.	Left in hole:	: 5 1/2" casing from 2,045' to 3,559'.	
		10 3/4" casing from surface to 309'.	
		•	
	8. I hereby certify that the information	shave is true and complete to the heat of level 1	
8. I hereby certify that the information above is true and complete to the best of my beautiful.	and the mindition	to the best of my knowledge and belief.	
8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	a L	•	
	GNED TO	TITLE Assistant District Manage	2-23-67
		1	
	$\cap \mathcal{U}$	V	
8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  IGNED TITLE Assistant Bistrict Manager DATE 2-23-67	PPROVED BY W.	Kumpay TITLE	DATE

CONDITIONS F APPROVAL, IF ANY: