	TED STATES HOBBS, NEW MEXICO 883 NT OF THE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	LAND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES	AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to d ATCLASS Use "APPLICATION FO	ill or to deepen or reentry to a different reservoir. R PERMIT—'' for such proposals	
SUBMIT IN TRIPLICATE 1. Type of Well Gas Well Gas Well Other 2. Name of Operator Conoco Inc.		 If Unit or CA, Agreement Designation 8. Well Name and No. 9. FUNITOR HELD SECOND
		3. Address and Telephone No. 10. Desta Drive STE 100W, Midland, TX 79705 (915)686-5424
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area EUNICE 7 RVRS QUEEN
		11. County or Parish, State
1980° FSL & 1980° FEL, SEC. 33	, T-225, R-36E, UNIT LTR 'J'	
CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPOR	LEA, NM
		T, ON OTHER DATA
Notice of Intent	Abandonment Recompletion	Change of Plans
XX Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice		Conversion to Injection
	χ other \tilde{C}/O & ACIDIZE	_ Dispose Water (Note: Report results of multiple completion or
give subsurface locations and measured and true verti	cal depths for all markers and zones pertinent to this work.)*	any proposed work. It wents directionally
- 1-20-93 MIRU. POOH W/ RODS. F	UMP AND TEG GIH W/ BIT CLEAN OUT TO	38001 (71 20)
-20-93 MIRU. POOH W/ RODS, F COH. GIH W/ PKR SET @ 35171.	UMP AND TEG GIH W/ BIT CLEAN OUT TO	38001 (1100 (1104))
-20-93 MIRU. POOH W/ RODS, F COH. GIH W/ PKR SET @ 35171.	UMP AND TBG. GIH W/ BIT CLEAN OUT TO ACID W/ 500g ACID & 1000# ROCK SALT GIH W/ 118 JTS 2 3/8" TBG, RODS AND PO	38001 (71 20)
-20-93 MIRU. POOH W/ RODS, F COH. GIH W/ PKR SET @ 35171.	UMP AND TBG. GIH W/ BIT CLEAN OUT TO ACID W/ 500g ACID & 1000# ROCK SALT GIH W/ 118 JTS 2 3/8" TBG, RODS AND PO	38001. CIRC CLEAN. FOLLOWED WITH 3000g MP RETURN WELL
-20-93 MIRU. POOH W/ RODS, F COH. GIH W/ PKR SET @ 35171.	UMP AND TEG. GIH W/ BIT CLEAN OUT TO ACID W/ 500g ACID & 1000# ROCK SALT GIH W/ 118 JTS 2 3/8" TEG, RODS AND PO	3800 CIRC CLEAN. FOLLOWED WITH 3000g MP RETURN WELL
1 hereby certify that the foregoing is true and correct Signed	UMP AND TBG. GIH W/ BIT CLEAN OUT TO ACID W/ 500g ACID & 1000# ROCK SALT GIH W/ 118 JTS 2 3/8" TBG, RODS AND PO	38001. CIRC CLEAN. FOLLOWED WITH 3000g MP RETURN WELL
1-20-93 MIRU. POOH W/ RODS. F OOH. GIH W/ PKR SET @ 3517 CID. RELEASE PACKER, POOH. O PRODUCTION -27-93 RDMO.	UMP AND TBG. GIH W/ BIT CLEAN OUT TO ACID W/ 500g ACID & 1000# ROCK SALT GIH W/ 118 JTS 2 3/8" TBG, RODS AND PO CONTRACTORY SPEC	3800 CIRC CLEAN. FOLLOWED WITH 3000g MP RETURN WELL
1 hereby certify that the foregoing is true and correct Signed	UMP AND TBG. GIH W/ BIT CLEAN OUT TO ACID W/ 500g ACID & 1000# ROCK SALT GIH W/ 118 JTS 2 3/8" TBG, RODS AND PO CONTRACTORY SPEC	FOLLOWED WITH 3000g MP RETURN WELL 1 Jana 1 1 ISaa

##