

UNITED STATES
DEPARTMENT OF THE INTERIORS
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other Instructions on re-DATE)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS 88240

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection Well	7. UNIT AGREEMENT NAME South Eunice Unit
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME South Eunice Unit
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. 57
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FWH - Unit Letter L	10. FIELD AND POOL, OR WILDCAT Eunice 7 Rvs Queen S
14. PERMIT NO. 30-025-09129	11. SEC., T. R., M., OR BLK. AND SURVEY OR AREA 33-22S-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU. G1H w/kit to top of retained at 3550' & POOH.
2. Log well w/ GR-CBL-VOL from 500' - 250'. Log TOC below 300' G1H w/ perf gun & perf 5 1/2" csq at 450' w/ 4 js pf. Establish circ w/ 9# brine. POOH.
3. G1H w/ 4 3/4" bit to 3550'. Pump 25 sxs class "C" cement to cap retained. Displace w/ 19 bbls 10#/gal mud. POOH to 3300'. Pump 50 bbls 10#/gal mud. POOH to 1600'. Pump 60 sxs class "C" cement. Displace w/ 6 bbls 10#/gal mud. POOH to 450'. Pump 50 sxs class "C" cement to surface. If csq was perforated, TAG 55 pump 150 sxs class "C" cement to surface. If cement does not circulate, pump 25 sxs cement down annulus. POOH.
4. Cut off csq 3' below ground level. Install P&A marker.
For further information contact Gay Vashler at 397-5866.

18. I hereby certify that the foregoing is true and correct

SIGNED DAVID F. FINNEY TITLE Administrative Supervisor DATE March 29, 1989

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE CHIEF, MINERAL RESOURCES DATE 4-11-89

CONDITIONS OF APPROVAL, IF ANY:

Subject to
Like Approval
by State

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM (Bureau of Land Management) (Department of the Interior)