

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-09129</u>
5. Indicate Type of Lease <u>Fee</u> STATE ☐ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection Well</u>	7. Lease Name or Unit Agreement Name <u>South Denise Unit</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Well No. <u>57</u>
3. Address of Operator <u>P. O. Box 460 - Hobbs, NM 88240</u>	9. Pool name or Wildcat <u>Denise 7 Rvrs Queen, S.</u>
4. Well Location Unit Letter <u>L</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>33</u> Township <u>22S</u> Range <u>36E</u> NMPM <u>Lea</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRR. G1H w/ bit to top of retained at 3550' & POOH.
2. Log well w/ GR-CBL-VDL from 500'-250'. If TOC below 300' G1H w/ perf gun & perf 5 1/2" csq at 450' w/ 4 1/2" spf. Establish circ w/ 9" brine. POOH.
3. G1H w/ 4 3/4" bit to 3550'. Pump 25 sxs class "C" cement to cap. retained. Displace w/ 19 bbls 10#/gal mud. POOH to 3300'. Pump 50 bbls 10#/gal mud. POOH to 1600'. Pump 60 sxs class "C" cement. Displace w/ 6 bbls 10#/gal mud. POOH to 450'. Pump 50 sxs class "C" cement to surface. If csq was perforated, pump 150 sxs class "C" cement to surface. If cement does not circulate, pump 25 sxs cement down annulus. POOH.
4. Cut off csq 3' below ground level. Install P&A marker. For further info contact Jay Vastler at 397-5866.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D. F. Finney TITLE Administrative Supervisor DATE March 27, 1987

TYPE OR PRINT NAME D. F. Finney TELEPHONE NO. (505) 397-5800

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:
nmocd-46bts(3) file

APR 3 1989

APPROPRIATE FIELD OFFICE
TO THE RECORDING OF
LAND OPERATIONS FOR THE C-103