

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		Seven Rivers Queen Unit
3. Address of Operator		8. Farm or Lease Name
P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No.
4. Location of Well		27
UNIT LETTER <u>E</u> , 1980 FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM		10. Field and Pool, or Wildcat
THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.		So. Eunice-7R/Q
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3512' GR		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>
Convert to WIW <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In accordance w/NMOCC order no. R4584, we propose to convert this well to water injection service as outlined below:

POH w/rods & tubing.
Make trip w/bit & scraper.
Add perfs 3763-67' w/2 JSPF.
Acidize perfs 3763-67' w/1500 gal 15% HCL-LSTNE acid.
Run Baker model AD-1 tension pkr, set @ 3650'.
Load annulus w/treated fresh water.

Injection will be in perforated interval 3700-3767'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED P.D. Sretches TITLE Dist. Drlg. Supv. DATE 10/3/73

APPROVED BY _____ TITLE _____ DATE _____