

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
 Orig&2cc: OCC Hobbs
 cc: Regional Office
 cc: file

HOBBS OFFICE O.C.C.
 MAY 28 11 51 AM '67

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Rodman M. Jones
9. Well No. 3
10. Field and Pool, or Wildcat Eunice South
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Sinclair Oil & Gas Company 3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER C 660' FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 22S RANGE 36E NMPM.	15. Elevation (Show whether DF, RT, GR, etc.) 3498' GR
--	---

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>

Blank-Off Queen formation 3697-3769'
 and perforate Seven Rivers

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Present PBTD 3780'
 Completed in Queen formation 3697-3769'.

PROPOSE TO: Run Packer and C.I. Bridge Plug, blank-off perms. 3697-3769' and test casing and plug.
 Perforate Seven Rivers w/2-3/8" shots @ approx. following intervals 3603-07-13-41-45-59-65-71'. Acidize w/approx. 1000 gals. mud acid.
 Sand Oil Frac perms. w/approx. 20,000 gals. refined oil and 20,000# sand. Swab well and place on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 5-25-67
 APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: