

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-09185
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. A-2614
7. Lease Name or Unit Agreement Name MCDONALD WN STATE
8. Well No. 6
9. Pool name or Wildcat JALMAT TANSILL YATES SR GAS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator ARCO OIL AND GAS COMPANY	
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	
4. Well Location Unit Letter <u>B</u> : <u>990</u> Feet From The <u>NORTH</u> Line and <u>2310</u> Feet From The <u>EAST</u> Line Section <u>36</u> Township <u>22S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3427.8'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3603'; OPEN HOLE 2903-3503'

TA AND HOLD WELL BORE FOR FUTURE USE

1. NOTIFY NMOCD 24 HOURS PRIOR TO TESTING CSG
2. MIRU
3. GIH AND SET CIBP MAXIMUM 50' ABOVE OPEN HOLE
4. LOAD HOLE w/TREATED FLUID AND TEST CIBP TO 500# AND CUT CHART
5. POH. LEAVE 1 JT HANGING. SI ALL VALVES
6. RDCL

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Operations Coordinator DATE 10/29/91
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: