| Form 9-331 a (Feb. 1951) | ~~ · · · · · · · · · · · · · · · · · · | , | Budget Bureau No. 42-R358.4. Approval expires 12-31-60. | | | |
|------------------------------------|--|-------|--|--------|--|--|
| X | (SUBMIT IN TRIPLICATE) UNITED | 1 | | 0133 • | | |
| | GEOLOGICAD SURVEY | | Unit | | | |
| | | 0:15 | | | | |
| SUN | DRY NOTICES AND REPORT | 'S ON | WELLS | | | |

| NOTICE OF INTENTION TO DRILL | | SUBSEQUENT REPORT OF WATER SHUT-OFF |
|--|---------|--|
| NOTICE OF INTENTION TO CHANGE PLANS | | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | - 27 62 | |
| <u>Cleanout, Set Liner</u> | XX | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

| Noyer 4-29 | | | | February 7 | | | | , 19 _57 | | | |
|------------|--------------------|------------|-----|------------|--------|------------|----------|-----------------|------------|---|----|
| Well No. | 5 | is located | 990 | ft | . fron | n [N] | line and | 990 | ft. from E | $\left\{ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\$ | 29 |
| ¥%/L | Sec 29 | | 22 | S | 36 |) 16 | | | | J | |
| C4 8 | Sec. and Sec. No.) | | (Tw | p.) | | (Range) | | (Meric | lian) | | |
| South | Bunice | • | | | Le | i . | | | ii ew | Maxico | |
| | (Field) | | | ((| County | or Subdiv | ision) | | (State or | Territory) | |

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is intended to clean out to 3340", set 300" of 4" OD slotted liner from 3040-3340". Liner slotted 3200-3330". Well will not be cleaned out to TD 3410".

A Subsequent report will be filed upon completion of work.

 I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

 Company
 Continental Oil Company

 Address
 Box 68

 Bunice, New Mexico
 By

 Title
 District Superint endent

U. S. GOVERNMENT PRINTING OFFICE 16-8437-6

na da serie Serie da ser Serie da ser

an an ann an Arthur