

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease
State ☐ Federal ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER: <u>Injection</u>	7. Unit Agreement Name <u>South Eunice Unit</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>South Eunice Unit</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>43</u>
4. Location of Well UNIT LETTER <u>I</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>east</u> LINE, SECTION <u>29</u> TOWNSHIP <u>22 S</u> RANGE <u>36 E</u> NMPM.	10. Field and Pool, or Wildcat <u>South Eunice, Seven</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: <u>Modify Injection Profile</u> ☒	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER: _____
PLUG AND ABANDON ☐ CHANGE PLANS ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRR. Pressure test backside to 500 psi for 30 mins.
2. Clean out to 3828'.
3. Run csg scraper to 3700'.
4. Run caliper from 3828'-3500'.
5. G-I H w/ cement dump bailer & dump 3sx of class "C" cmt w/ 2% CaCl₂ to plug well back from 3828'-3800'. Wait on cement 1 hr & tag cement top at 3800'. POOH.
6. Perf interval 3767'-70' w/ 4 JS PF for total of 12 shots. Perf interval 3693'-98', 3706'-20, 3744'-54' & 3784'-88' w/ 2 JS PF for total of 66 shots. POOH.
7. Dump 15 ft³ of 12/20 sand down csg to plug well back from 3800'-3690'. G-I H w/ bailer & tag top of sand at 3690'. If top of sand is below 3690', dump additional sand. If top of sand is above 3690', POOH.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DF FINNEY TITLE Administrative Supervisor DATE 12/9/87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY: 7 MOC'D (3) ARCO (2) Amoco (2) Chevron (1) File

DEC 11 1987