

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-229

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name Seven Rivers Queen Unit
3. Address of Operator P.O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 44
4. Location of Well UNIT LETTER D 660 FEET FROM THE north LINE AND 660 FEET FROM THE west LINE, SECTION 2 TOWNSHIP 23S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Langlie Mattix 7 Riv.Q
15. Elevation (Show whether DF, RT, GR, etc.) 3497' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Install Retrievable Bridge Plug

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to install RBP in 5½" OD Csg to isolate perfs 3730'-34', 3740'-43' & 3752'-57' temporarily in the following manner:

1. Rig up, install BOP, POH w/completion assembly.
2. Install retrievable BP in 5½" OD Csg @3723' and temporarily isolate perfs 3730'-57'.
3. RIH w/tbg, rods and pump & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. L. Homa TITLE Sr. Dist. Prod. Supv. DATE 6/10/75

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: