

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-229
7. Unit Agreement Name Seven Rivers Queen Unit
8. Farm or Lease Name Seven Rivers Queen Unit
9. Well No. 44
10. Field and Pool, or Wildcat Langlie Mattix-Seven Rivers
12. County Lea

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Atlantic Richfield Company
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	4. Location of Well UNIT LETTER <u>D</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>23S</u> RANGE <u>36E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3497' GR	16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p align="center"><b>NOTICE OF INTENTION TO:</b></p> <p>PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>          TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>          PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p align="center"><b>SUBSEQUENT REPORT OF:</b></p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>          COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>          CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/></p>	
---	--	---	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3800', PBD 3797'. Present perforations 3652-62', 3665-73', 3678-84', 3692-3700', 3706-16'. Propose to add perfs to same zone and acidize in the following manner:

1. POH w/completion assy.
2. CO to PBD w/sd pump.
3. Run bit & scraper to PBD.
4. Perf additional section 3730-34', 3740-43' & 3752-57'.
5. Run trtg pkr. Spot acid across perfs 3730-3757'. Set pkr @ 3725' & acidize w/a total of 2000 gals 15% HCL-ISTNE acid & ball sealers.
6. Swab back load. POH w/pkr. Re-run completion assy & return to production.

I, Thereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY: