

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name Seven Rivers Queen Unit
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 41
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>23S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat <u>So. Eunice 7RQ</u>
15. Elevation (Show whether DF, RT, GR, etc.) 3459.7' RKB		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Convert to WIW</u> <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In accordance w/NMOCC order no. R4589, we propose to convert to water injection service as outlined below:

POH w/tubing.
Make trip w/bit & scraper to PBD.
Run Baker Model AD-1 tension packer on 2-3/8" cmt lined tubing & set pkr @ 3600'.
Load annulus w/treated fresh water.
Injection will be in perforated interval 3652'-3755'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

D. D. Butcher

TITLE

Dist. Drlg. Supv.

DATE

10/29/73

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: