

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002509225
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1327
7. Lease Name or Unit Agreement Name MEXICO "E" COM.
8. Well No. 2
9. Pool name or Wildcat JALMAT TANSIL YATES 7 RIVERS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER	
2. Name of Operator Texaco Exploration and Production Inc.	
3. Address of Operator P.O. Box 730, Hobbs, NM 88241-0730	
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>2</u> Township <u>23-S</u> Range <u>36-E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3460' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET CIBP @ 3525', VAP W/35' CMT. (PBTD 3490')

- 1) PERF JALMAT 3326'-3436' w/2 JSPI (114 HOLES)
 - A) ACIDIZE PERFS W/2500 GALS 15% NEFE ACID-MAX 890#, MIN 110#.
 - B) FRAC W/35000 GALS X-LINK GEL CARRYING 127,500# SAND-MAX-1950#, MIN-965#, ISIP-50#
- 2) SET RBP @ 3252', PERF YATES 3026'-2172' W/2 JSPI (168 HOLES)
 - A) ACIDIZE PERFS W/500 GALS 15% NEFE, MAX-800#, MIN-300#.
 - B) FRAC W/47,500 GALS 30# BORATE X-LINK GEL W/143,500# SAND-MAX-4937# MIN-359#, AIR-32 BPM
- 3) RETRIEVE RBP, PLACE WELL ON PRODUCTION.
- 4) POTENTIAL 4-1-91, PUMP 0 OIL, 1 WTR, 206 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L.W. Johnson TITLE Engr. Asst. DATE 9-19-91

TYPE OR PRINT NAME L.W. Johnson TELEPHONE NO. (505) 397-0426

(This space for State Use) APPROVAL SIGNED BY JERRY SEXTON
APPROPRIATE SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: