DISTRICTI P.O. Box 1980, Hobbs, NM 8210 P.O. Box 2088 P. Box 2088 P.O. B	Submit 3 Copies to Appropriate District Office State of New Mexico Energy, Minerals and Natural Resources Department	artment Form C-103
Santa Fe, New Mexico 87504-2088 S. Indicate Type of Lase Santa Fe, New Mexico 10 Fee Feminary Santa Fe, New Mexico 87504-2088 S. Indicate Type of Lase Santa Fe, New Mexico 87504-2088 S. Indicate Type of Lase Santa Fe, New Mexico 87504-2088 S. Indicate Type of Lase Santa Fe, New Mexico 10 Feminary Santa Fe, New Personal	DISTRICT! P.O. Box 1980, Hobbe, NM 88240 OIL CONSERVATION DIVIS	Revised 1.1.89
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOOD PROPOSALS TO PRILL OR TO DEFEN OR PLUG BACK TO A DIFFERENT RESERVOR USE "APPLICATION FOOR PERMIT" 1. Type of Well: ONE WELL ON THE STATE OF PROPOSALS TO OR PERMIT (FORM C-101) FOR SUCH PROPOSALS) 2. Name of Operator Hall J. Rasmussen Operating, Inc. 3. Address of Operator 6. Desta Drive, Suite 5850, Midland, Texas 79705 4. Well Location Unit Letter L. : 990 Feet From The West Line and 1650 Feet From The South Line Section 3 Township 23 S Range 36 E NAMEM Lea County 10. Exercise (Form Active Depth REPORT, RE, RT, GR, etc.) 3. Address of Operator 4. Well Location Unit Letter L. : 990 Feet From The West Line and 1650 Feet From The South Line Section 3 Township 23 S Range 36 E NAMEM Lea County 10. Exercise (Form Weller Depth RE, RT, GR, etc.) 3. Address of Operator 10. Exercise (Form Weller Depth RE, RT, GR, etc.) 3. Address of Operator 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF Intention TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORABILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent dutals, and give pertinent dutes, including estimated date of starting any proposed work) SEE RULE 113. Start Date - 3/27/89 Completion date - 3/10-89 POOH w/ tbg; RIH w/ bailer and clean out; acid 22 w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in	DISTRICT II P.O. Box 2088	WELL API NO.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: COST	DISTRICT III	5. Indicate Type of Lease
DIFFERENT RESERVOR. USC 'APPLICATION FOR PERMIT' 1. Type of Well: ONE COLON C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ONE State "A" A/C.1 1. Type of Well: OTHER 2. Name of Operator 4. Well Decador 1. Lesse Name or Unit Agreement Name State "A" A/C.1 1. Lesse Name or Unit Agreement Name 1.		
OTHER State "A" A/C.1	DIFFERENT RESERVOID TO DEEPEN OR PLUG BACK	. Lease Name or Unit Agreement Name
Name of Operator Hall J. Rasmussen Operating, Inc. See the proposed of Completed Operator Hall J. Rasmussen Operating, Inc. See the proposed of Completed Operator Hall J. Rasmussen Operating, Inc. See the proposed of Completed Operator Hall J. Rasmussen Operating, Inc.	OIL GAS WELL	State "A" A/C.1
6 Desta Drive, Suite 5850, Midland, Texas 79705 9. Pool name or Wildcat Jalmat TNSL-YTS-7R (Pro Gas) Unit Letter L : 990 Feet From The West Line and 1650 Feet From The Line Socion 3 Township 23 S Range 36 E NMPM Lea County 10. Elevation (Show whicher DF, RKE, RT, GR, etc.) 3491 GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Start Date - 3/27/89 Completion date - 3/10-89 POOH w/ tbg; RIH w/ bailer and clean out; acid 22 w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in	2 Name of Operator	
O Desta Drive, Suite 5850, Midland, Texas 79705 1. Well Location Unit Letter L : 990 Feet From The West Line and 1650 Feet From The South Line Socion 3 Township 23 S Range 36 E NMPM Lea County 10. Elevation (Show whether DF, RKB, KT, GR, stc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER SERVICE 1103. POOH w/ tbg; RIH w/ bailer and clean out; acid 22 w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in	S. Address of Operator	• • • • • • • • • • • • • • • • • • •
Unit Letter L : 990 Feet From The West Line and 1650 Feet From The South Line Socion 3 Township 23 S Range 36 E NMPM Lea County 3491 GL 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Start Date - 3/27/89 Completion date - 3/10-89 POOH w/ tbg; RIH w/ bailer and clean out; acid ze w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in	6 Desta Drive, Suite 5850, Midland, Texas 79705	9. Pool name or Wildcat
Township 23 S Range 36 E NMPM Lea County 10. Elevation (Show whether DF, RKB, KT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK		Jaimat TNSL-YTS-7R (Pro Gas)
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Start Date - 3/27/89 Completion date - 3/10-89 POOH w/ tbg; RIH w/ bailer and clean out; acid ze w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in Before: TA'd	Township 23 S	26 F
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: CASING TEST AND CEMENT JOB OTHER:	3491 GL	ec.)
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Start Date - 3/27/89 Completion date - 3/10-89 POOH w/ tbg; RIH w/ bailer and clean out; acid*ze w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in Before: TA'd	NOTICE OF INTENTION TO:	ice, Report, or Other Data
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OF CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed Start Date - 3/27/89 Completion date - 3/10-89 POOH w/ tbg; RIH w/ bailer and clean out; acid*ze w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in Before: TA'd		
OTHER: CASING TEST AND CEMENT JOB	TEMPORARILY ABANDON CHANCE DI AND	ALIERING CASING
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Start Date - 3/27/89 Completion date - 3/10-89 POOH w/ tbg; RIH w/ bailer and clean out; acid*ze w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in Before: TA'd	PULL OR ALTER CASING COMMENCE DE	- : 200 ARD ABANDONMENT
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed Start Date - 3/27/89 Completion date - 3/10-89 POOH w/ tbg; RIH w/ bailer and clean out; acid ≠ ze w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in Before: TA'd		ND CEMENT 10B
POOH w/ tbg; RIH w/ bailer and clean out; acid ze w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in Before: TA'd	12. Describe Proposed or Completed Operations (Clearly state all pertinent details and aircraft)	
POOH w/ tbg; RIH w/ bailer and clean out; acid*ze w/ 1500 gals. NEFe. RIH w/ tbg & rods. Put in pump. No fluid - shut in Before: TA'd	Start Date - 3/27/89 Completion date - 3/10-89	s, including estimated date of starting any proposed
	POOH w/ tbg; RIH w/ bailer and clean out; aciding and the	500 gals. NEFe. RIH w/ tbg & rods.
After Charles	Before: TA'd	
After. Shut in temporarily	After: Shut in temporarily	

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Agent	10/2//20
TYPEOR PRINT HAME Jay D. Cherski	DATE 10/24/89
(This space for State Use) CRIGINAL SIGNED BY JERRY SEXTON	ТЕГЕРНОМЕ NO. 915-687-166
DISTRICT I SUPERVISOR	OCT 3 0 1989
CONDITIONS OF APPROVAL, IF ANY:	DATE

CONDITIONS OF APPROVAL, IF ANY: