STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	<u> </u>
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

				Revised 10-1-7
SANTA PE		SANTA FE, NEW	MEXICO 87501	
FILE				Sa. Indicate Type of Lease
U.S.G.S.				State X Fee
OPERATOR				5. State Oil & Gas Leage No.
				B-1506
	SUNDRY NOTIC	ES AND REPORTS ON	WELLS	
EINT 3EU TOH 00)		MILL OR TO DEEPEN OR PLUG &		
•				7. Unit Agreement Name
OIL X GA	OTHER-			
2. Name of Operator			8. Form or Lease Name	
ARCO Oil and	Gas Company			Seven Rivers Queen Un
. Address of Operator				9. Well No. 46
Box 1610, Midland, Texas 79702				
4. Location of Weil			10. Field and Pool, or Wildcat	
UNIT LETTER B	330	FEET FROM THE North	LINE AND 1980	Langlie Mattix 7 Rvvs 9n
Wall Certex				
East	LINE, SECTION 3	TOWNSHIP	36E	
786	-			
		15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
		3519 GR		Lea (
6.	Check Appropria	ate Box To Indicate N	ature of Notice, Report or	Other Data
NOT	ICE OF INTENTIO			ENT REPORT OF:
				·
PERFORM REMEDIAL WORK		PLUE AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ASAMDON	╡	_	COMMENCE DRILLING OPHS.	PLUG AND AGANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	casing test and cement jos Deepen in sa	Cti-ulata
PACE OF MELCH CHOICE		_	Deepen in sa	ime zone a Stimulate
OTHER				
OTHER				
7. Describe Proposed or	Completed Operations (C	Clearly state all pertinent det	ails, and give pertinent dates, incli	iding estimated date of starting any propos
	Completed Operations (C	Clearly state all pertinent det	ails, and give pertinent dates, incli	iding estimated date of starting any propos
(7. Describe Proposed or (work) SEE RULE 1 (0)).			iding estimated date of starting any propos
17. Describe Proposed or work) SEE RULE 1103	RU PU. POH	w/CA. RIH w/4-3/4	" bit.	iding estimated date of starting any propos
11-18-86 11-19-86	RU PU. POH DO to 3784'.	w/CA. RIH w/4-3/4 Cut 2-1/2" core	" bit.	iding estimated date of starting any propos
11-18-86 11-19-86 11-20-86	RU PU. POH DO to 3784'.	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826'	" bit. to 3786'.	
11-18-86 11-19-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0	" bit. to 3786'. DH 3776-3826' w/6500 g	als DGA 215 & 500 gals
11-18-86 11-21-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
11-18-86 11-19-86 11-20-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
11-18-86 11-21-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
11-18-86 11-21-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
7. Describe Proposed or 6 work) SEE RULE 1 for 11-18-86 11-19-86 11-20-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
7. Describe Proposed or 6 work) SEE RULE 1 for 11-18-86 11-19-86 11-20-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
11-18-86 11-21-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
7. Describe Proposed or 6 work) SEE RULE 1 for 11-18-86 11-19-86 11-20-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
7. Describe Proposed or 6 work) SEE RULE 1 for 11-18-86 11-19-86 11-20-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
7. Describe Proposed or 6 work) SEE RULE 1 for 11-18-86 11-19-86 11-20-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
11-18-86 11-21-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
11-18-86 11-21-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
11-18-86 11-21-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals
7. Describe Proposed or 6 work) SEE RULE 1103 11-18-86 11-19-86 11-20-86 11-21-86	RU PU. POH DO to 3784'. TD'd 4-3/4" Acid frac pe 10# GBW w/1	w/CA. RIH w/4-3/4 Cut 2-1/2" core hole @ 3826' rfs 3672-3766' & 0 ppg RS. RIH w/CA	" bit. to 3786'. OH 3776-3826' w/6500 g Return to production	als DGA 215 & 500 gals n 11-22-86.

RECEIVED

JAN 2.8 1987

OCO OFFICE

HOBBS OFFICE