



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. LC 030557 (a)
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Subsequent Report of PE & Recomplete	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Farney A-5

December 30, 1958

Well No. 6 is located 1980 ft. from XXX line and 1980 ft. from E line of sec. 5

SE/4 Sec. 5
(1/4 Sec. and Sec. No.)

23 S
(Twp.)

36 E
(Range)

RAIP
(Meridian)

Jalnet
(Field)

Lee
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3481 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

BEFORE WORKOVER - TD 3860' Dolo, PB 3772', DF 10', Elev 3481' DF. Pay Seven Rivers 3715-69'. Cog Pt 5 1/2" at 3860'. Perfs 3715-45' and 3752-69'. Well was permanently shut down prior to workover.

WORK DONE - Squeezed intervals 3715-45' and 3752-69' w/250 Gx. Set retainer at 3705'. Perf'd 3444-62', 3472-90', 3494-3510', 3530-40', 3562-90' w/2 jets per Ft. Fraced w/16,000 Gal treatment. Failed to recover load oil.

AFTER WORKOVER - TD 3860' Dolo, PB 3705'. Perfs Yates 3444-62', 3472-90', 3494-3510', 3530-40', and 3562-90'. Project unsuccessful. Well returned to former status as PSD. Workover started 12-11-58, completed 12-28-58.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Bunice, New Mexico

By _____

Title District Superintendent