

COPIES RECEIVED	
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator A. P. Campbell (Amica Life & Casualty, Agent)	8. Farm or Lease Name Christmas
3. Address of Operator 10 E. 3rd, Roswell, New Mexico 8001	9. Well No. 1
4. Location of Well UNIT LETTER <u>C</u> <u>600</u> FEET FROM THE <u>N</u> LINE AND <u>2</u> FEET FROM THE <u>1</u> LINE, SECTION <u>36</u> TOWNSHIP <u>36</u> S RANGE <u>1</u> NMPM.	10. Field and Pool, or Wildcat Jalisco Yates
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Log

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

I intend to Plug Subject well as follows:

Spot 100' Plug 3000' to 3020'
Shoot off to pull 4 1/2" casing (est. 3000')
Spot 100' plug to 4 1/2" Stub
Spot 100' plug to 1650' to 1700' (top of salt)
(100' plug 3310' to 3410', base of salt, if typeset)
spot 100' plug 240' to 340' (surface shot to 250')
10 ss. at surface w/ dry hole marker
and between plugs
24 hr. advance notice to WOC.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Agent (Bonding Company)

DATE

1-16-74

APPROVED BY

TITLE

Dist. Sec.

DATE

1/28/74

CONDITIONS OF APPROVAL, IF ANY:

Please copy to Casualty, Millers, Inc. 3000 Lovelock St., Hobbs, New Mexico 8001