

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Budget Bureau N-1004-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

LC-029864A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ RECEIVED OCT 3 1 10 AM '89

2. NAME OF OPERATOR

Conoco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 460 - Holders, NM 86240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

Unit A 990' FNL * 990' FEL

14. PERMIT NO.

30-025-09276

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3488' DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sauciger A-8

9. WELL NO.

#3

10. FIELD AND POOL OR WILDCAT

Jalmat Yates Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 8, T23S, R36E

12. COUNTY OR PARISH 13. STATE

Chia NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Notify Holders BLM Office

MIRU. ND wellhead NU BOP. Set cmt. Retainer @ 3340', pump 65 sx cement to fill up 4-3/4" open hole and 5-1/2" casing from 3700' to 3100', displace w/13 bbls mud. Spot last 25 sx of cmt. on top by displacing w/5-bbls mud (TOC @ 3100'. Pump 11 sx cement and displace w/8 bbls mud to spot plug across top of salt from 1610' to 1504'. Perf 5-1/2" csg. @ 410'. Establish circ. up 8-5/8" x 5-1/2" annulus, pump 120 sx cmt to fill annulus. NDBOP, cut off csg. strings, fill w/cmt. and erect P+H marker. Restore location

18. I hereby certify that the foregoing is true and correct

SIGNED

W.W. Baker

W.W. Baker

TITLE Administrative Sup'r.

DATE

Sept. 29, 1989

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

10-20-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side