

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 09279
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  State A A/C 1
---

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

8. Well No. 100
--------------------

2. Name of Operator  
Clayton W. Williams, Jr., Inc. 4910

9. Pool name or Wildcat <i>Kanglee Matty Skaggs</i> Jalmat Tansill Yts - 7R 23100
--

3. Address of Operator  
Six Desta Drive, Suite 3000 Midland, Texas 79705

4. Well Location  
Unit Letter H : 1980 Feet From The North Line and 990 Feet From The East Line  
Section 9 Township 23S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
GL - 3471

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/92 - Set CIBP @ 3141'. Dumped 2 sx cement on CIBP.  
9/10/92 - Isolate csg leaks from 300-730'. Received verbal plugging instructions from Jerry Sexton - OOI.  
9/12/92 - Displace 9.5 PPG gelled brine from 3100' to surface.  
9/14/92 - Spotted a 20 sx balanced plug from 700-800'. Break circulation down csg and up 9-5/8", 7" annulus. Pumped 200 sx Class C w/2% CaCl2 down csg. Lost circulation out annulus. Pumped 40 sx Class C w/2% CaCl2 down annulus. Held pressure for 1 hour. Dug out and cut wellhead and anchors. Set Plug and Abandon Marker.

\*WELL PLUGGED AND ABANDONED 9/14/92\*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE <u>David Grafe</u>	TITLE <u>Petroleum Engineer</u> DATE <u>9/17/92</u>
TYPE OR PRINT NAME <u>David G. Grafe</u>	TELEPHONE NO. <u>682-6324</u>

(This space for State Use)	OIL & GAS INSPECTOR
APPROVED BY <u>Charles L. Patten</u>	DATE <u>AUG 13 1993</u>
CONDITIONS OF APPROVAL, IF ANY:	