

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-09294
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A A/C 1
8. Well No. 56
9. Pool name or Wildcat Langlie Mattix - 7Rvr, Qu, S
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL - 3438'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Clayton W. Williams, Jr., Inc.
3. Address of Operator Six Desta Drive, Suite 3000 Midland, Texas 79705	4. Well Location Unit Letter L : 1980 Feet From The S Line and 660 Feet From The W Line Section 10 Township 23S Range 36E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/92 - Set CIBP @ 3430'. Dumped 2 sx cement on CIBP.

9-14 thru 9-15-92

Isolate csg leak @ 465'. (Slow Collar leak). Received verbal plugging instructions from Jerry Sexton - OCD. Displaced 9.5 PPG gelled Brine from 3400' to surface. Perf 5-1/2" csg 2 SPF @ 350'.

9/16/92

Spotted 25 sx balanced plug from 407-645'. Broke circulation down csg and up 8-5/8, 5-1/2" annulus. Pumped 90 sx Class C + 2% CaCl2 down csg and up annulus. Circulated 30 sx cement to pits. Dug out and cut wellhead and anchors. Set plug and abandon marker.

**\*WELL PLUGGED AND ABANDONED (9/16/92)\***

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Grafe TITLE Petroleum Engineer DATE 9/17/92  
TYPE OR PRINT NAME David G. Grafe TELEPHONE NO. 682-6324

(This space for State Use)

OIL & GAS INSPECTOR

AUG 13 1993

APPROVED BY Charles Perrin TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

C'm

E<sup>2</sup>