STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION P. O. BOX 2088	Form C-103 Revised 10-1-78
SANTA FE, NEW MEXICO 87501	
FILE	5a. Indicate Type of Lease
U.\$.G,\$,	State K Fee
LAND OFFICE	5. State Oil & Gas Lease No.
OPERATOR	
SUNDRY NOTICES AND REPORTS ON WELLS	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.	7. Unit Agreement Name
1	,, o
OIL X WELL OTHER-	8. Farm or Lease Name
2. Name of Operator	1 7
Sun Exploration & Production Co.	State "A" A/C 3 A
3. Address of Operator	9. Well No.
P. O. Box 1861, Midland, Texas 79702	4
4. Location of Weil	10. Field and Pool, or Wildcat
UNIT LETTER B 660 FEET FROM THE NORTH LINE AND 2310 FEET	Langlie-Mattix
UNIT LETTER D FEET FROM THE LINE AND	
10 23_S 36_E	
THE EAST LINE, SECTION 10 TOWNSHIP 23-S RANGE 36-E	mww. {///////////////////////////////////
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
111111111111111111111111111111111111111	Lea
3469' GR	
Check Appropriate Box To Indicate Nature of Notice, Report of	or Other Data
	UENT REPORT OF:
MOTICE OF INTENTION TO	
PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDONMENT
TEMPORARILY ABANDON COMMENCE DRILLING OPMS.	1
PULL OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JOB	perfs X
OTHER add	<u> </u>
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent actains, and give pertinent actas, and	
2_12_85 POH w/rods & pump	
2-12-85 POH w/rods & pump	
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup	s to 3729' Howco spot 2 bbls
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup	s to 3729' Howco spot 2 bbls
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" W 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" W 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" W 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900,	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900,	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" W 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD.	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 &
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" W 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD.	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 &
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" W 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, F 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd r	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, F 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd r w/5½ RDG pkr on 2-7/8 tbg to 3400.	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, F 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd r w/5½ RDG pkr on 2-7/8 tbg to 3400.	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, B 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd m w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot 1½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good by	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/pall action w/press incr
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, B 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd m w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot 1½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good by	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/pall action w/press incr
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, F 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd r w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot ½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good b 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu- 2660' /12000 sals Pumpel 30 + 26000# 20/40 sd.	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/oall action w/press incr
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, F 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd r w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot ½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good b 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu- 2660' /12000 sals Pumpel 30 + 26000# 20/40 sd.	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/oall action w/press incr
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, B 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd n w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot ½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good b 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu 3621' to 3668' w/12000 gals Purgel-30 + 26000# 20/40 sd. 2-20-85 POH TIH w/bulldog bailer on 2-7/8" WS tag & CO sd fr 3651 to	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/oall action w/press incr
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, B 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd m w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot 1½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good b 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu 3621' to 3668' w/12000 gals Purgel-30 + 26000# 20/40 sd. 2-20-85 POH TIH w/buildog bailer on 2-7/8" WS tag & CO sd fr 3651 to	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/oall action w/press incr
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, F 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd n w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot ½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good b 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu 3621' to 3668' w/12000 gals Purgel-30 + 26000# 20/40 sd. 2-20-85 POH TIH w/bulldog bailer on 2-7/8" WS tag & CO sd fr 3651 to TIH w/bailer to 3400'	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/ oall action w/press incr oalls to 1000# Howco frac perf
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, R 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd n w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot 1½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good R 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu 3621' to 3668' w/12000 gals Purgel-30 + 26000# 20/40 sd. 2-20-85 POH TIH w/bulldog bailer on 2-7/8" WS tag & CO sd fr 3651 to TIH w/bailer to 3400' 2-21-85 Lwr bailer, tag & Co Sd 3685-3729 PBTD PU to 3600 2-22-85 Lwr bailer CO sd from 3717-3729 PBTD POH LD 2-7/8" WS TIH w/2-	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/ oall action w/press incr oalls to 1000# Howco frac perf
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, F 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd r w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot 1½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good b 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu 3621' to 3668' w/12000 gals Purgel-30 + 26000# 20/40 sd. 2-20-85 POH TIH w/bulldog bailer on 2-7/8" WS tag & CO sd fr 3651 to TIH w/bailer to 3400' 2-21-85 Lwr bailer, tag & Co Sd 3685-3729 PBTD. PU to 3600 2-22-85 Lwr bailer CO sd from 3717-3729 PBTD POH LD 2-7/8" WS TIH w/2- TR 2677' SN 36/2' PIH w/2"y1½" yump on 66 rod string	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/ oall action w/press incr oalls to 1000# Howco frac perf
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, F 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd r w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot 1½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good b 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu 3621' to 3668' w/12000 gals Purgel-30 + 26000# 20/40 sd. 2-20-85 POH TIH w/bulldog bailer on 2-7/8" WS tag & CO sd fr 3651 to TIH w/bailer to 3400' 2-21-85 Lwr bailer, tag & Co Sd 3685-3729 PBTD. PU to 3600 2-22-85 Lwr bailer CO sd from 3717-3729 PBTD POH LD 2-7/8" WS TIH w/2- TR 2677' SN 36/2' PIH w/2"y1½" yump on 66 rod string	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/ oall action w/press incr oalls to 1000# Howco frac perf
2-12-85 POH w/rods & pump 2-13-85 POH w/2-3/8" pumping setup 2-14-85 POH w/bit TIH w/3 jts 2-7/8" tail pipe on 5½" pkr & 2-7/8" w 15% NEFEHCL acid from 3729' to 3677' Set pkr @ 3564' press annulus to 3677' to 3729' w/5000 gals 15% NEFE HCL acid. 2-15-85 REL pkr & POH, go PB w SD 3729-3663, Go ran GR-CCL 3662-2900, clean out PB SD @ 3663, could not wash SD. 2-16-85 RU power swivel & clean out PB SD 3663-3672 circ hole clean, R 3635-68 1 JSPF 40 holes w 4 csg gun 23 G.C. Stuck gun @ 3672 on 2nd n w/5½ RDG pkr on 2-7/8 tbg to 3400. 2-17-85 Lwr pkr to 3668, Hal spot 1½ bbls NEFEHCL 3668-3608, PU & set Hal acdz perfs 3621-3668 w/4000 gals 15% NEFEHCL + 60 RCNBS/had good R 800-2600. 2-19-85 rel pkr lwr & tag PB sd @3673' PU & set pkr @ 3378' press annu 3621' to 3668' w/12000 gals Purgel-30 + 26000# 20/40 sd. 2-20-85 POH TIH w/bulldog bailer on 2-7/8" WS tag & CO sd fr 3651 to TIH w/bailer to 3400' 2-21-85 Lwr bailer, tag & Co Sd 3685-3729 PBTD PU to 3600 2-22-85 Lwr bailer CO sd from 3717-3729 PBTD POH LD 2-7/8" WS TIH w/2-	S to 3729' Howco spot 2 bbls 500# Howco acidize OH from RIH w/4-3/4 bit, attempted to OH, Go Perf 3621-3626 & cun, fished w/overshot/RIH pkr @ 3408, trap 500 on csg/ oall action w/press incr oalls to 1000# Howco frac perf

MAR 2 9 1985

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

MAR 28 1985