

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30 025 09301
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER

Name of Operator Clayton Williams Energy, Inc.

Address of Operator Six Desta Drive, Suite 3000 Midland, Texas 79705

Lease Name or Unit Agreement Name State A AC 3 A

Well No. 3

Pool name or Wildcat Langlie Mattix 7 Rvrs Queen GB

Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>23S</u> Range <u>36E</u> NMPM <u>Lea</u> County

Elevation (Show whether DF, RKB, RT, GR, etc.) 3460' - GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>TA Status</u> <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Load 8-5/8" casing with field salt water. (CIBP set at 3603')
- 2) Pressure test casing from surface to 3603' to 500 psi for 30 minutes.
(Record test on chart for OCD subsequent report)
- 3) Temporarily abandon wellbore for future use.

This Approval of Emergency
Abandonment Expires 7-16-2002

OK!
7/8/97
RWH

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>Robin S. McCarley</u>	TITLE <u>Production Analyst</u>	DATE <u>06-25-97</u>
TYPE OR PRINT NAME <u>Robin S. McCarley</u>		TELEPHONE NO. <u>915) 682-6324</u>

(This space for State Use)

ORIGINAL FILED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY	TITLE	DATE
-------------	-------	------

CONDITIONS OF APPROVAL, IF ANY: