

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-09315
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A AC 1 11792
8. Well No. 83
9. Pool name or Wildcat Langlie Mattix 7 Rvrs Queen GB 37240

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Clayton Williams Energy, Inc. 25706
3. Address of Operator Six Desta Drive, Suite 3000 Midland, Texas 79705	4. Well Location Unit Letter C : 660 Feet From The North Line and 2310 Feet From The West Line Section 11 Township 23S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR - 3431'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Work will commence upon OCD Approval

- CIBP set @ 3400' w/35' cement on CIBP (12/13/93)
- Circulate hole w/10 PPG gelled brine from CIBP to surface
- Perforate 7" casing @ ± 330'.
- Circulate cement down 7" casing and up the 7"/9-5/8" annulus to surface. (110 sx Class "C" cement w/2% CaCl2)
- Cut 7" and 9-5/8" casing 3' below GL. Set P & A marker. Cut deadmen. Remove all junk from location. **Plug and Abandon Wellbore**

PLUGGING OPERATIONS MUST BE NOTIFIED 24 HOURS BEFORE THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David G. Crafe TITLE Senior Operations Engineer DATE 09/01/94

TYPE OR PRINT NAME David G. Crafe TELEPHONE NO. 682-6324

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 06 1994