

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

PERMIT IN TRIP DATE
(Other instructions on reverse side)

RECEIVED

LEASE DESIGNATION AND SERIAL NO.
L C - 030556B

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Stevens B
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, NM 88240	9. WELL NO. #1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1650' FNL - Unit C Unit C	10. FIELD AND POOL, OR WILDCAT Jalmat Yates Gas
14. PERMIT NO. 30-C25-09324	11. SEC., T., R., M., OR S.W. 1/4, AND SURVEY OR AREA Sec. 12, T23S, R36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-18-89 GIH w/CIBP, set @ 2930'. Spot 6 x Class "C" cmt on top of CIBP. PU to 1407. Spot 5 bbls 15% HCl-NE-FE. GIH w/4" HSC csg. gun. Perf. 4 JSPPF @ 1406. GIH w/ 5 1/2" cmt. retainer; set @ 1252'. Est. circ. Pump 85 bbls Class "C" cmt. Ran temp. Survey. Tag cmt @ 1069'. Survey indicated cmt 500' csg fr surface in 7-5/8". POH to 50'. Spot cmt plug to surface. Cut off w/H. Set dry hole marker. Restore location.

18. I hereby certify that the foregoing is true and correct

SIGNED

Maxine Simpson W.W. Baker Jr. Adm. Supervisor

DATE

12/29/89

(This space for Federal or State office use)

APPROVED BY

Original and Copy to Supervisor

TITLE

Field Supervisor

DATE

1-5-90

CONDITIONS OF APPROVAL, IF ANY:

Approved by [Signature]
Lic. No. [Blank]
Surveyed [Blank]

*See Instructions on Reverse Side

RECEIVED

JAN 11 1990

CCO
HOBBS OFFICE