

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Int well</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-030556(b)</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	7. UNIT AGREEMENT NAME <u>NMFU</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>Unit A</u> <u>660' FNL & 660' FEL</u>	8. FARM OR LEASE NAME <u>Stevens B</u>
14. PERMIT NO. <u>30-025-09329</u>	9. WELL NO. <u>8</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT <u>Langlie Mathix 7Rurs Queen</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 12 - 23S - 36E</u>
	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☒

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- ① MIRU on 11-5-85. CO 81' of fill to 3657'. Located leaks between 725' & 786' and slight leak @ 455'.
- ② Perf w/4 shots @ 750'. Pmp 125 sxs class "C" w/2% CaCl₂. Sqz to 800#. Tag cmt @ 317. Drill cmt to 725'. Press. test to 500# but bled off to 225#.
- ③ With to 746'. Spot 8bbbls 15% HCL, perf from 740'-745' w/2 JSPF. Set pkr @ 200'. Pmp 20bbbls HCL. Rel pkr and set @ 725'. Pmp 20 bbls 15% HCL.
- ④ Reset pkr @ 508' and pmp 50 sxs class "C" w/2% CaCl₂. Rel pkr and set @ 200' pmp 50 sxs class "C" w/2% CaCl₂.
- ⑤ Couldn't get get sqz, so repeated step #4. Sqzd to 650#.
- ⑥ Tag cmt @ 263'. DO cmt to 554'. Test to 500# for 15 min w/no leak off. Ran bit and scraper to 825'. Press. test to 500#, bled down to 225#.
- ⑦ Ran RBP & set @ 700'. Tested to 1000#. Set pkr @ 695'. Estab. pmp in rate into leak. Reset pkr @ 200'. Pmp 50 sxs class "C" Thix-tropic.
- ⑧ Tag cmt @ 284'. DO to 470'. Press. test csq to 500# w/no leak off. Rig down on 11/22/85.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

11-25-85

(This space for Federal or State office use)

APPROVED FOR RECORD

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 2 1985

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO

It is a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Dr. J. C. ... (2) ... (2) ... (1) File

RECEIVED

DEC 3-1985

O.C.D.
HOBBS OFFICE