

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
 Orig&2cc: OCC, Hobbs
 cc: Regional Office
 cc: file

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Sinclair Oil & Gas Company	7. Unit Agreement Name
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240	8. Farm or Lease Name King WN	9. Well No. 1
4. Location of Well UNIT LETTER L 2310 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 23S RANGE 36E NMBM.	10. Field and Pool, or Wildcat Langlie Mattix	12. County Lea
15. Elevation (Show whether DF, RT, GR, etc.) 3405' GR		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Temporarily Abandoned

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-27-67 Set PSI blank-off plug @ 3450' in Langlie Mattix tubing. Backed off tubing @ 3264', moved tubing 1 foot and stuck, ran chemical cutter to 3215' and pull 3215' 2-3/8"OD tubing. Washed over fish to 3268' and pulled 49' of fish. Left 2-3/8"OD EUE tubing collar looking up @ 3264', PSI blank-off plug @ 3450' and Brown Oil Tool BP-4 Retreivable B.P. Pkr @ 3492'. Set packer below Jalmat perms. @ 3247' and tested casing and plug to 1000# for 30 mins. Tested O.K. Ran 2-3/8"OD EUE 4.7# J-55 tubing to 3032' w/1 - 25/32" seat nipple, swabbed Jalmat perms. 3088-3206' and completed as single completion in Jalmat Gas zone after temporarily abandoning Langlie Mattix oil zone 3613-3666'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 3-20-67

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: