

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator  
**TEXAS PACIFIC OIL CO., INC.**

Address of Operator  
**P. O. Box 1069 - Hobbs, New Mexico**

Location of Well  
UNIT LETTER **B**, **660** FEET FROM THE **North** LINE AND **1980** FEET FROM  
THE **East** LINE, SECTION **13** TOWNSHIP **23-S** RANGE **36-E** NMPM.

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. <b>NM 2A</b>	
7. Unit Agreement Name	
8. Farm or Lease Name <b>State "A" A/c-1</b>	
9. Well No. <b>57</b>	
10. Field and Pool, or Wildcat <b>Langlie Mattix</b>	
12. County <b>Lea</b>	

15. Elevation (Show whether DF, RT, GR, etc.)  
**3380' GR**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in, rig up. Pull rods and tubing.
2. Perf. 3454-64-80-86-93-99-3509-15-18-23-36-44'.
3. Set packer @ 3400'; RBP @ 3550'. Acidized w/1500 gal. 15% NE. Pull tbgs. & pkr.
4. Frac w/20,000 gal. gelled brine / 30,000# 20/40 sand. Flush.
5. Pull RBP. Run tubing and swab. Run pump and rods. Test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED Sheldon Ward TITLE Area Superintendent DATE 4-6-71

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT DATE APR 9 1971

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

APR 8 1971

OIL CONSERVATION CO. INC.  
HOBBS, N. M.