

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
 Successors Old  
 C-102 and C-103  
 Effective 1-1-65  
 APR 29 11 31 AM '66

5a. Indicate Type of Lease  
 State ☒ Fee ☐  
 5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>TEXAS PACIFIC OIL COMPANY</b>	8. Farm or Lease Name State "A" A/c-1
3. Address of Operator <b>P.O. Box 1069 - Hobbs, New Mexico</b>	9. Well No. <b>65</b>
4. Location of Well UNIT LETTER <b>D</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>760</b> FEET FROM THE <b>West</b> LINE, SECTION <b>23</b> TOWNSHIP <b>23</b> RANGE <b>36</b> NMPM.	10. Field and Pool, or Wildcat <b>Langlie Mattix</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3375'</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pulled rods and tubing.
2. CO to 3524'. Perforate 3/8" holes 3451-58-70-76-3502-03-06-07-15'.
3. Ran tubing and packer @ 3431'. Spot 125 gals. acid across perfs.
4. Acidize w/1000 gals. 15% NE acid.
5. Pull tubing and packer. SOT w/25,000 gals. lse. oil + 25,000# 20/40 sd., 1/20 Adomite.
6. Ran pump & rods.

4-14-66 819 BL0TR

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Richard S. Stary* TITLE **Absa Superintendent** DATE **4-28-66**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: