

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name ANNIE CHRISTMAS	
9. Well No. 1	
10. Field and Pool, or Willow Wantz Drinkard/Granite Wash	
12. County LEA	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEX OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - L" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator SUN OIL COMPANY
3. Address of Operator P. O. Box 1861, Midland, Texas 79701
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 22-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3348.7 GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Additional perfs & stimulation within same formations.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Prior to start of W.O. Baker model "K" dual snapset pkr @ 4928, Otis WB pkr W/OSSD @ 7248.
Drinkard perfs - 6833-6927
Granite Wash perfs - 7272-7296

Granite Wash 2-10 to 2-14-76: MIRU DA&S Kill well w/crude & diesel. POOH w/short string. Rel. Model "K" dual pkr. @ 4828 & POOH. Set SN plug in WB pkr @ 7248. Western perfed 7217, 18, 19, 23, 25, 33, 35, 37 w/3-1/8" O.D. Wesjet Super. Run FB pkr to 7237'. Acidize W/2000 gal. 15% NEHCL. POOH W/FB pkr. Run tbg W/OSSD without lugs, Otis "RH" pkr. and OSSD w/lugs. Set lower OSSD on WB pkr. @ 7248. Set Otis "RH" pkr @ 7181. Rel. upper seal divider and POOH.

Drinkard 2-17 to 2-19-76: Ran FB pkr. & RBP. Set RBP @ 6750, FB @ 6138. Western perfed 6291, 93, 95; 6307, 11, 13, 17, 19, 23, 25; 6446, 48, 69, 71; 6613, 21, 23 w/1-9/16" OD Wesjet magnum. Howco acidized w/4250 gal. 15% NEHCL. POOH W/FB & RBP.

Ran parallel tbg. strings with Otis RDH pkr. Set long string on RH pkr @ 7181 with OSSD. Set Otis RDH pkr. @ 4849. Ran short tbg string and latched into RDH pkr. @ 4849.
Long string: TS. 7254, OSSD'S @ 7180 & 7254, ported coupling @ 7248.
Short String: TS. 6144, J-latch sub 4844.
Packers: Otis WB @ 7254, Otis RH @ 7181, Otis RDH @ 4849.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles Gray</u>	TITLE PRORATION ANALYST	DATE 6-10-76
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		