

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name Walter Lynch
3. Address of Operator P. O. Box 1861, Midland, Texas 79701	9. Well No. 1-11
4. Location of Well UNIT LETTER K 1980 FEET FROM THE West LINE AND 1980 FEET FROM THE South LINE, SECTION 1 TOWNSHIP 22-S RANGE 37-E N.M.P.M.	10. Field and Pool, or Wildcat DRINKARD
15. Elevation (Show whether DF, RT, GR, etc.) GR. 3357'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Installation of 1.315" tbg. etc.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 6-2-75 MIRU DA&S. Install Hydril BOP & un-jay 2" tubing from pkr. @ 5004'.
- 6-3-75 POOH w/2" OD Butt. & lay down. POOH w/7" RDH pkr. & 2-7/8" tbg.
- 6-4-75 Un-jay overshot seal divider from pkr. 7141' & POOH. RIH w/1443' 2-3/8" NUE 10 Rd. W/Sp. Cfr. Cplg. & overshot seal divider, SN & 2-3/8" x 1.315" shoe & 36 jts. I. J. tbg.
- 6-5-75 Finish w/longstring & 1.315" tbg. w/dual RDH pkr. Space out w/6000# on P.L. pkr. @7145'. Displace tbg w/lse oil & prep to run 2" tbg.
- 6-6-75 Finish in hole w/2" OD Butt W/J-latch seal assbly. Space out in pkr @ 4982'. Land tbg. w/6000# compr. N.U. head.
- 6-7-75 Ret. 1-3/8" Otis plug from N nipple @ 7140 w/sand line, run 1-1/2" Otis plug & set in N nipple @ 4997 in UT string. Tested to 2,000#. Set RDH pkr @ 4982' & test 7" csg. & pkr to 700 psi. Pull 1-1/2" plug from UT & swab LT - Well kicking. Swabbing UT.
- 6-8 to 7-1-75 Testing & running PLT
WELL NOW DUALY COMPLETED IN ACCORDANCE W/NMOCC ORDER No. R-4993.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles Gray</u>	TITLE <u>Charles Gray-Proration</u>	DATE <u>7-7-75</u>
APPROVED BY <u></u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		