

COPIES RECEIVED		
DISTRIBUTION		
DATE		
U.S.		
D OFFICE		
DIATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☐ Fee ☒
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Paddock
9. Well No. 22
10. Field and Pool, or Wildcat Paddock
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-DRILL OR TO PLUG BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PERMIT TO DRILL OR TO RE-DRILL OR TO PLUG BACK TO A DIFFERENT RESERVOIR.

WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator Exxon Corporation
Address of Operator Box 1600, Midland, TX. 79702
Location of Well
UNIT LETTER F 1980 FEET FROM THE N LINE AND 1980 FEET FROM W LINE, SECTION 1 TOWNSHIP 22-S RANGE 37-E NMPH.

15. Elevation (Show whether DF, RT, CR, etc.)
3360' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
PERMANENTLY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
ON ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

Describe the Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

1. Set cast iron BP at 5050'.
2. Set 10 sack cmt. plug at 5050'.
3. Cut 5 1/2" csg. at 2570 and pulled csg.
4. Set 30 sack plug at 2610. Set 70 sack plug at 1200', and 35 sack plug at 350'.
5. Set 10 sack plug at surface.
6. Install dry hole marker as required by NMOCC.
7. C-103 will be forwarded when location is cleaned and leveled.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature: <i>C. D. Jackson</i>	TITLE: Unit Head	DATE: 6-25-79
OIL & GAS INSPECTOR		
Signature: <i>[Signature]</i>	TITLE:	DATE:
ADDITIONS OF APPROVAL, IF ANY:		