		•
		Form C-103
NO. OF COPIES RECEIVED		Supersedes Old C-102 and C-103
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	
FILE		5a. Indicate Type of Lease
U.S.G.S.		State Fee Fee
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		37721
SUNDR	Y NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR FROM	T INVITCE AND THE PROPERTY OF PLUG BACK TO A DIFFERENT RESERVOIR. POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1. GAS		— '
WELL WELL	OTHER-	8. Farm or Lease Name
2. Name of Operator	12 0 · C	Paddock (San Angelo) Unit
2. Name of Operator Humble OII	Keta Lo.	9. Well No.
3. Address of Operator	1 1 TO 1 TO 1 TO 1	13
Box 1600 - 1	Midland, Texas	10. Field and Pool, or Wildcat
UNIT LETTER A	660 FEET FROM THE N LINE AND 660 FEET	FROM
0.11. 42.11		
E LINE SECTION	DN 2 TOWNSHIP ZZ-S RANGE 37-E	MPM. (())))))))
THE	•	12. County
	15. Elevation (Show whether DF, RT, GR, etc.)	Lea
	3366 DF	
16. Check	Appropriate Box To Indicate Nature of Notice, Report o	r Other Data
	NTENTION TO: SUBSEQU	JENT REPORT OF:
NOTICE OF II	VI ENTION 101	_
<u></u>	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JOB	_
PULL OR ALTER CASING	OTHER	
OTHER		
17 Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any propose
work) SEE RULE 1103.	pump and tubing. Schlumburg	ger perf well
Pulled rods	Dump and tubing. Schlumburg	Ter per
from 5/13 6	nd pumpfor test Pulled pum	and acidined
11 - rnds ai	nd oumptor lest Fully Pri	
109,	gal NE acid. Max iccopsi	min 900 ps/,
Well W 3000	sign The acid. That was to	1011 70
AIR 37 BPI	m. Reran pump and retu	Med Well 10
production	<i>/</i>	
	•	
		•
		•