
NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES



	31				JUS IV		, . .	BBS OFFICE
begin. A co advisable, or ed, and work	opy will be ret the rejection should not be	turned to the	sender on v	which will rent of t	l be given he nian sui	the approval, wi	before the work spith any modification in as approved should the Rules and Re	d he follow
the Commiss	sion.	Ind	licate nature	of notic	e by check	ing below:		
NOTICE OF INTENTION TO TEST CASING SHUT-OFF				x	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL			
NOTICE OF INTENTION TO CHANGE PLANS					NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING			
NOTICE OF INTENTION TO REPAIR WELL					NOTICE OF INTENTION TO PLUG WELL			
NOTICE OF	INTENTION	TO DEEPEN	WELL					
		Nidla	and, Texa	8			September	9. 1946
			-		Pla	ice	Date	
Santa Fe, No Gentlemen:			certain worl	k as desci	ribed belov	v at the		
	Hl & Refi		any N	. N. S	tate "S"		1 No. 9 in	NE/4 of SK/4
Compan	y or Operator		Le	1.50				
	-	26-5			N. M. P. K	[.,Fausa	ock	Field.
Lo	<u> </u>		Coun	•			. =	
						LAN OF WO)RK	
	MOTIOTI IN							
	FOLLOW IT	nstruction	NS IN THE	RULES .	AND REGU	JLATIONS OF T	HE COMMISSION	
	FOLLOW IF	STRUCTION			AND REGU S FOLLO		HE COMMISSION	
SIZE	AMOUNT	wei ght		SING A	s FOLLO			Plug on Bottom
SIZE 5-1/2*			SET CA	SING A	s FOLLO	S: OTAL DEPTH	No. Sacks &	5:17 PM.
	AMOUNT	WEIGHT	SET CA	SING A	S FOLLOF	S: OTAL DEPTH OF WELL	NO. SACKS & MAKE CEMENT 200 Sx. Trinity Slow Set Neat 100 Sx. Trini Slow Set 3	5:17 PM. 9-7-46
5-1/2*	AMOUNT	WEIGHT	SET CA	SING A	S FOLLOF	S: OTAL DEPTH OF WELL	NO. SACKS & MAKE CEMENT 200 Sx. Trinity Slow Set Neat 100 Sx. Trini	5:17 PM. 9-7-46
5-1/2* Halliba	AMOUNT 5195.691	WEIGHT	SET AT 52091	FORM L	S FOLLOW	S: NOTAL DEPTH OF WELL 5209	NO. SACKS & MAKE CEMENT 200 Sx. Trinity Slow Set Neat 100 Sx. Trini Slow Set 3	5:17 PM. 9-7-46
5-1/2* Hallibu	AMOUNT 5195.691 arton methods casing	WEIGHT	SET AT 52091	FORM L	S FOLLOW	S: OTAL DEPTH OF WELL 5209 * 9-9-46.	NO. SACKS & MAKE CEMENT 200 Sx. Trinity Slow Set Neat 100 Sx. Trini Slow Set 3% Howcogel	5:17 PM. 9-7-46
5-1/2* Halliba	AMOUNT 5195.69' arton methods casing	WEIGHT 11# od used. with 100	SET AT 52091	FORM L	S FOLLOW	S: OTAL DEPTH OF WELL 5209 * 9-9-46.	NO. SACKS & MAKE CEMENT 200 Sx. Trinity Slow Set Neat 100 Sx. Trini Slow Set 3% Howcegel	5:17 PM. 9-7-46
5-1/2* Hallibu Will te	AMOUNT 5195.69' arton methods casing	WEIGHT 11# od used. with 100	SET AT 52091	FORM L	S FOLLOW	S: NOTAL DEPTH OF WELL 5209 * SELE OIL & F Comp Divis	NO. SACKS & MAKE CEMENT 200 Sx. Trinity Slow Set Neat 100 Sx. Trini Slow Set 3% Howcogel	BOTTOM 5:17 PM. 9-7-46
Hallibu Will te	AMOUNT 5195.69' arton methods casing	weight 11# od used. with 100	SET AT 5209°	FORM L	ATION THE	S: NOTAL DEPTH OF WELL 5209 * SELE OIL & B Comp Comp Divis Send communic	NO. SACKS & MAKE CEMENT 200 Sx. Trinity Slow Set Neat 100 Sx. Trini Slow Set 3% Howcogel	BOTTOM 5:17 PM. 9-7-46
Hallibu Will te	AMOUNT 5195.69° nrton methods casing SEP 1 Collows:	weight 11# od used. with 100	SET AT 5209°	FORM L	7 P. M., HUB	S: NOTAL DEPTH OF WELL 5209 * SELE OIL & B Comp Comp Divis Send communic	NO. SACKS & MAKE CEMENT 200 Sx. Trinity Slow Set Neat 100 Sx. Trini Slow Set 3% Howcogel EFINING COMPAN any or Operator ation Superinter ations regarding we	BOTTOM 5:17 PM. 9-7-46