

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-934	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Exxon Corporation		8. Farm or Lease Name New Mexico "S" State	
3. Address of Operator Box 1600, Midland, TX 79701		9. Well No. 20	
4. Location of Well UNIT LETTER <u>E</u> <u>2100</u> FEET FROM THE <u>North</u> LINE AND <u>500</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> NMPM.		10. Field and Pool, or Wildcat Drinkard	
15. Elevation (Show whether DF, RT, GR, etc.) RDB 3381		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Killed Tubb gas zone w/brine.
- Pulled tbg. and Packer. Set pkr. at 6200'. Perf. 5½" csg. from 6260-6437' w/21 shots. Reset packer at 6310 and acid frac from 6442-6490 w/15,000 gal. polymulsion plus 17,000 gal. HCL acid. Set BP 6330 and pkr. at 6180, acid frac perfs. from 6280-6293 w/7,500 gal. polymulsion plus 9,000 gal. 20% HCL acid. Pulled BP. Ran 2-3/8 tubing and packer set at 6195'. Drinkard zone tested 705 Mcf/D, 16/64 ck, TP 800.

Tubb gas zone placed on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>D L Clemmer</u>	TITLE <u>Unit Head</u>	DATE <u>1-19-76</u>
APPROVED BY <u>Jerry</u>	TITLE <u>SENIOR</u>	DATE <u>1-19-76</u>
CONDITIONS OF APPROVAL, IF ANY:		