

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Brunson "C"
8. Well No. 6
9. Pool name or Wildcat Drinkard & Tubb
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> Drinkard GAS WELL <input checked="" type="checkbox"/> Tubb OTHER
2. Name of Operator John H. Hendrix Corporation
3. Address of Operator P. O. Box 3040, Midland, TX 79702-3040
4. Well Location Unit Letter <u>I</u> : <u>2080</u> Feet From The <u>South</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>3</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Zone Abandon Drinkard ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Zone ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/ tbg.
2. Recover Model D packer at 6400'.
3. Squeeze Drinkard OH 6448 - 6550' & Tubb perms. 5840 - 6160'.
4. Drill out to 6200'.
5. Reperforate Tubb fr. 5840 to 6160'.
6. Acidize and frac.
7. Well will be a Tubb single with the Drinkard ~~plugged~~ ^{Zone} and abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ronnie H. Westbrook TITLE Vice-President DATE 4/12/96
TYPE OR PRINT NAME Ronnie H. Westbrook (915) 684-6631

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE APR 16 1996
CONDITIONS OF APPROVAL, IF ANY: