


Drinkard capacity than the test of April, 1954 since all load oil has now been recovered. No attempt was made to obtain bottom hole pressure data since the well is pumping.

As mentioned above this data indicates no communication between the Blinebry and Drinkard pays.

Also attached is a diagrammatic sketch of the mechanical installation actually installed and used to segregate production from the two zones.

Yours very truly,



Ralph L. Hendrickson
Field Superintendent

RVC:bc

Attachments - 1

cc: New Mexico Oil Conservation Commission
Hobbs, New Mexico