

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
EXXON CORPORATION ATTN: REGULATORY AFFAIRS

3. Address and Telephone No.
P. O. BOX 1600 MIDLAND, TX 79702 (915) 688-6748

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SECTION 3, T22S-R37E

5. Lease Designation and Serial No.

37721

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
PADDOCK (SAN ANGELO) UNIT 24

9. API Well No. **3002520398** 09993

10. Field and Pool, or Exploratory Area
PADDOCK

11. County or Parish, State
LEA NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection



SUBSTANCE RELEASE REPORT

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ON SEPTEMBER 13, 1995 APPROXIMATELY 22.5 BARRELS OF OIL WERE RELEASED DUE TO UNCONTROLLED PRESSURE RELEASE WHILE PULLING STUCK PUMP AT THE WELL REFERENCED ABOVE. THE PUMP AND RODS WERE STUCK WITH PARRAFIN. HOT OIL WAS PUMPED DOWN THE ANNULUS IN AN ATTEMPT TO LOOSEN THE PARRAFIN. THE PUMP WAS PULLED AND TRAP PRESSURE BLEW OUT.

THE AREA AFFECTED WAS WASHED WITH "PETRO-GREEN". FERTILIZER HAS BEEN APPLIED TO THE AREA FOR REMEDIATION.



14. I hereby certify that the foregoing is true and correct.

Signed

Sally R. Urby

Sally R. Urby
Title **SR-Staff Technical Assist**

Date **09/22/95**

(This space for Federal or State Office use)

Approved by

Conditions of approval, if any

Title

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representation as to any matter within its jurisdiction.

