DISTRICT I

OF CONSERVATION DIVISION ———

-		_		_
R	evise	ď	1-1	1-89

P.O. Box 1980, Hobbs, NM 88240 2040 Pacheco St.	WELL API NO.
DISTRICT II P.O. Drawer DD. Artesia, NM 88210 Santa Fe , NM 8750	5 30-025-10013
	5. indicate Type of Loase STATE FEE XX
DISTRICT III 1000 Rio Brizos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	BACK TO A  7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil. GAS WELL X WELL OTHER	Corrigan, H.
2. Name of Operator	8. Well No.
Collins & Ware, Inc	8 .
508 West Wall, Suite 1200, Midland, Texas 7970	9. Pool same or Wildcat 1 Blinebry Oil & Gas (06660)
	and 2080 Feet From The East Line
0/ 22c 77	F
Section U4 Township 223 Range 37	NM/M C
//////////////////////////////////////	
11. Check Appropriate Box to Indicate Nature of	Notice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA	L WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMEN	CE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING T	EST AND CEMENT JOB
OTHER: OTHER:_	Perf and Treat Blinebry
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103.	nt dates, including estimated date of starting any proposed
11/04/97 Run GR/CCL from 6350 to 5324, tie into fax CIBP at 6300'. GIH with 4" casing guns and 5725' - 5744' and 5660' - 5669' with a total	perf Blinebry with 1 JSPF from
11/05/97 Set RBP at 5848 and packer at 5690. Acidize Ferchek acid and 30 ball sealers. Achieved at 5550. Acidize perfs 5660 — 5669 with 950 Achieved ball out.	ballout. Reset RBP at 5690 and packer
11/12/97 Frac Blinebry (5660-5744) with Delta Frac in 175,730# sand.	4 stages using 55,000gals Delta Frac and
175,730# sand. 11/14/97 Run 2 3/8 tubing to 5774*, SN at 5742*, and	TAC at 5304' with 9 points tension. Run
175,730# sand.	TAC at 5304' with 9 points tension. Run
175,730# sand  11/14/97 Run 2 3/8 tubing to 5774*, SN at 5742*, and  2" x a 1/2" x 12* RHBC pump. Put well on pr  I borday cordiy that the information above is true and complete to the bost of my knowledge and belief.	TAC at 5304' with 9 points tension. Run
175,730# sand.  11/14/97 Run 2 3/8 tubing to 5774", SN at 5742", and 2" x a 1/2" x 12" RHBC pump. Put well on pr  I bordby cordify that the information above is true and complete to the bost of my knowledge and bolief.	TAC at 5304' with 9 points tension. Run oduction.
175,730# sand.  11/14/97 Run 2 3/8 tubing to 5774*, SN at 5742*, and 2" x a 1/2" x 12* RHBC pump. Put well on pr  I borday cordiy that the information above is true and complete to the bost of my knowledge and bodief.  SKONATURE TITLE Prod	TAC at 5304' with 9 points tension. Run oduction.  uction Supervisor 12/15/97
175,730# sand.  11/14/97 Run 2 3/8 tubing to 5774*, SN at 5742*, and 2" x a 1/2" x 12* RHBC pump. Put well on pr I bereby certify that the information above is true and complete to the best of my knowledge and belief.  SKONATURE Prod  TYPE OR FRINT NAME Dianne Sumrall  (Thus space for State Use)  OBIGINAL SHE'VE DEC. STATES WILLIAMS	TAC at 5304' with 9 points tension. Run oduction.  uction Supervisor 12/15/97

