

State of New Mexico  
Energy, Minerals and Natural ResourcesForm C-103  
Revised March 25, 1999~~District I~~

1625 N. French Dr., Hobbs, NM 88240

~~District II~~

811 South First, Artesia, NM 88210

~~District III~~

1000 Rio Brazos Rd., Aztec, NM 87410

~~District IV~~

2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO.

30-025-10016

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name:

Brunson B

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

OXY USA WTP Limited Partnership 192463

3. Address of Operator

P.O. BOX 50250 MIDLAND, TX 79710-0250

4. Well Location

Unit Letter I : 1980 feet from the South line and 810 feet from the East line

Section

4

Township 22S Range 37E

NMPM

County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

BRUNSON B-1

NOTIFY NMOCD OF INTENT TO P&A 10/11/00. MIRU PU 10/12/00, RDWH, NU BOP. RIH & SET CIBP @ 6675', SPOT 5sx CMT, WOC. RIH & TAG @ 6640', SPOT 9.5#MLF FROM 6640-5530', POOH. RIH & SET CIBP @ 5530', SPOT 5sx CMT, WOC. RIH & TAG @ 5494', POOH. SPOT 9.5#MLF FROM 5494-4953'. POOH TO 5140', SPOT 25sx CMT W/ 2% CaCl<sub>2</sub>, POOH, WOC. RIH & TAG @ 5031', SPOT 50sx CMT W/ 2% CaCl<sub>2</sub>, POOH, WOC. RIH & TAG @ 4516', SPOT 45sx CMT W/ 2% CaCl<sub>2</sub>, POOH, WOC. RIH & TAG @ 4427', SPOT 45sx CMT W/ 2% CaCl<sub>2</sub>, POOH, WOC. RIH & TAG @ 4045', CIRC HOLE W/ 9.5#MLF. RIH & PERF @ 2938', M&P 45sx CMT, POOH, WOC. RIH & TAG @ 2730', SPOT 25sx CMT W/ 2% CaCl<sub>2</sub>, POOH, WOC. RIH & TAG @ 2195', RIH & PERF @ 364', M&P 120sx CMT, CIRC CMT TO SURFACE. RDPU 10/21/00. DUG OUT CELLAR, CUT OFF WH & ANCHORS, INSTALL DRY HOLE MARKER, CLEAN LOCATION, WELL P&A'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE REGULATORY ANALYST

DATE 3/22/01

Type or print name

DAVID STEWART

Telephone No. 915-685-5717

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any:

C-103