	र्ग	1					
NO. OF COPIES RECEIVED							
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION				Form C+101 Revised 1-1-654		
SANTA FE	4				5A. Indicate Type of Lease		
FILE		·			STATE		
U.S.G.S.						& Gas Louse No.	
LAND OFFICE							
OPERATOR	· · · ·				mm	mmmm	
APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK							
APPLICATIO	N FUR PERMIT TU	DRILL, DELFEN, C	IN FLUG DACK		. Unit Agre	ement Name	
					•	.*	
DRILL DEEPEN X PLUG BACK					8. Farm or Leuse Name		
					Brunson		
WELL X WELL OTHER ZONE ZONE ZONE ZONE ZONE ZONE						9. Well No.	
Zia Energy, Inc.						# 3	
J. Address of Operator						10. Field and Pool, or Wildcat	
P.O. Box 2219, Hobbs, NM 88240					Penrose - Skelly		
L Location of Well 0 660 South					<u>IIIII</u>		
UNIT LETTER LOCATED FEET FROM THE LINE							
AND 1980 FEFT FROM	THE East LIN	E OF SEC. 4 - TW	P. 225 RGE. 3	7E NMPM			
	MUIIIIIII				12. County		
///////////////////////////////////////					Lea		
<u> </u>					//////		
///////////////////////////////////////							
IIIIIIIIIIIIIII.		())))))))))))))))))))))))))))))))))))		19A. Formation	:	20, Rolary or C.T.	
			3950	Graybur		Rev. circ.	
21. Elevations (Show whether DF,	RT, etc.) 21A. Kind	& Status Plug. Bond 21	-			. Date Work will start	
3435° GR	Blank	cet on file	Eunice well	Service		7/8/85	
23.	P	ROPOSED CASING AND	CEMENT PROGRAM				
SIZE OF HOLE	SIZE OF CASING WEIGHT PER FOOT SETTING DEPTH SACKS		I SACKS OF	CEMENT	EST. TOP		
6*	45"	10.5	3950 50			Top of liner	
) 	 		 	
1. Rig up Eunic	e Well Servio	ce and ABC Re	ntal reverse	e circuia	1	equipment.	
2. Pull rods an	d tubing. Go	עד א הסבטי עד כ די המשמת	A 39501		L COTTS	ars on	
2 3/8" tog. 3. Pull 4 3/4"	Deepen from	(PDTD)/47 (er Ream ho	le to 6'	• to 30	950'. Pull	
J. Pull 4 J/4" underreamer.		J UNDER TEAM	er. Reamine			///	
4. Run comp. Ne	ntron. Bamma	Ray, Caliper	logs.				
5. Run 400 $4\frac{1}{2}$	10.5# casin	cement li	ner using 50	sxs.			
6. Perforate zo	nes of poros	ity and stimu	late as requ	ired by	hole (conditions.	
7. Place well o	n production	to test.		·			
/• 11400 0011 0	. producerous						
,			•				
,			•				
ABOVE SPACE DESCRIBE PF	OPOSED PROGRAM: IF	PHOPOSAL IS TO DEEPEN OF	R PLUG BACK, GIVE DATA	Dh present prod	UCTIVE ZONE	AND PROPOSED NEW PRODUC	
I A BOVE SPACE DESCRIBE PF IVE ZONE, GIVE BLOWOUT PREVENT	ER PROGRAM, IF ANY.			DN PRESENT PROC	UCTIVE ZONE	AND PROPOSED NEW PRODU	
ABOVE SPACE DESCRIBE PF	on above is true and com	plete to the best of my kn	pwledge and belief.	DN PRESENT PROC)UCTIVE ZONE	AND PROPOSED NEW PHODU	
I A BOVE SPACE DESCRIBE PF IVE ZONE, GIVE BLOWOUT PREVENT	on above is true and com	plete to the best of my kn	pwledge and belief.		 יז	·····	
i ABOVE SPACE DESCRIBE PF ive zone, give blowout prevent hereby certify that the informati igned	on above is true and comp		pwledge and belief.			AND PROPOSED NEW PRODUC	
i ABOVE SPACE DESCRIBE PF ive zone, give blowout prevent hereby certify that the informati igned <u>MJ</u> <u>Me</u> (This space for	on above is true and complete	plete to the be st of my kn 	pwledge and belief.		ate7	/5/85	
ABOVE SPACE DESCRIBE PF IVE ZONE, GIVE BLOWOUT PREVENT hereby certify that the informati igned	on above is true and comp State Use)	plete to the be st of my kn Title	pwledge and belief. Engineer		ate7	/5/85	
ABOVE SPACE DESCRIBE PF IVE ZONE, GIVE BLOWOUT PREVENT hereby certify that the informati igned	on above is true and comp State Use)	plete to the be st of my kn Title	pwledge and belief.		ate7	·····	
i ABOVE SPACE DESCRIBE PF ive zone, give blowout prevent hereby certify that the informati igned <u>MJ</u> <u>Me</u> (This space for	on above is true and comp State Use) ICD BY JERRY SEXTOR ICD BY JERRY SEXTOR	plete to the be st of my kn Title	pwledge and belief. Engineer		ate7	/5/85	
ABOVE SPACE DESCRIBE PF IVE ZONE. GIVE BLOWOUT PREVENT hereby certify that the information igned	on above is true and comp State Use) ICD BY JERRY SEXTOR ICD BY JERRY SEXTOR	plete to the be st of my kn Title	pwledge and belief. Engineer		ate7	/5/85	