## State of New Mexico Energy, Minerals & Natural Resources Department

Form C-103 Revised 1-1-89

District Office	,		
<u>DISTRICT I</u>	OIL CONSERVATION DIVISION P. O. Box 2088 Santa Fe, NM 7504-2088		WELL API NO.
1625 French Drive Hobbs, NM 88240			30-025-10042
DISTRICT II			5. Indicate Type of Lease STATE FEE
P. O. Drawer DD, Artesia, NM 88210	<b>54.11.</b> 1501 2000		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
CUNDDY NOTICE	EC AND REPORTS ON MEI	1.0	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name Rinewalt
(FORM C-1	01) FOR SUCH PROPOSALS.)		Kinewait
1 Type of Well: OIL GAS GAS	7		
WELL WELL	OTHER		
2. Name of Operator			8. Well No.
The Wiser Oil Company			1
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico (505) 392-9797			9. Pool name or Wildcat  Ponrosa Skally Grayburg
4. Well Location	Hobbs, New Mexico (303) 3	92-9191	Penrose Skelly Grayburg
4. Well Excalled			
Unit Letter D: 660	Feet From The North	Line and 660 F	eet From The West Line
	225	270	an my
Section 4 To	ownship 22S Ran 10. Elevation (Show whether Di		NMPM Lea County
	10. Elevation (Show whether Di	r, M.D, Mr, OM, etc.)	
11. Check	Appropriate Box to Indicate 1	Nature of Notice, Re	port, or Other Data
NOTICE OF INTE	ENTION TO	SUBSI	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	FLOG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEI		ENT JOB L	
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
11/03/99 MIRU Tyler Well Service. POH w/pump & rods. Tag. @ 3637'. POH w/tbg. Mud anchor full of sand. RIH w/bailer & clean out to 3700'. POH w/bailer. RIH w/2-3/8" tbg. Bottom tbg. @ 3640'. RIH w/rods & 2" x 1-1/4" x 12' pump. Left well pumping to Battery. RDMO			
11/22/99 MIRU Pool Well Service. POH w/pump & rods. NU BOP. POH w/tbg. Clean sand out of mud anchor. RIH w/2-3/8" tbg. SN @ 3570'. RIH w/rods & 2" x 1-1/4" x 12' pump. Left well pumping to Battery. RDMO.			
1/4 X 12 pump. Let wen pumping to battery. Replace.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE MUNI QO THANH		TITLE Production Tech	h II DATE December 10, 2001
TYPE OR PRINT NAME   Mary Jo Turne	r		TELEPHONE NO. (505) 392-9797
(This space for State Use)			
		ARIGINAL SIGNE	D BY
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:		PATILE KATT	D BY DATE MAR 1 2 2002
COMBITIONS OF THE ROTTING IT PARTS.		DETROLEUM ENO	- ~ 100(

PETROLEUM ENGINEER

205