

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| | |
|--------------------------------|---|
| 5a. Indicate Type of Lease | |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐

1. Name of Operator

Gulf Oil Corporation

2. Address of Operator

Box 670, Hobbs, New Mexico 88240

3. Location of Well

UNIT LETTER I, 2086 FEET FROM THE South LINE AND 554 FEET FROM

THE East LINE, SECTION 5 TOWNSHIP 22-S RANGE 37-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

L. I. Baker

9. Well No.

3

10. Field and Pool, or Wildcat

Tubb

15. Elevation (Show whether DF, RT, GR, etc.)

3439' GL

12. County

Lea

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER Abandon Tubb zone and complete in ☐

Paddock

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6300' PB.

Pull producing equipment. Set retainer at 5950' and squeeze Tubb perforations 5998' to 6240' with approximately 150 sacks of Class C cement. WOC 18 hours. Test squeezed perforations with 500#, 30 minutes. Perforate Paddock zone in 7" casing in the approximate interval 5100' to 5400'. Treat new perforations with 1000 gallons of 15% NE acid. Swab and clean up and return well to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. F. Berlin

TITLE Area Engineer

DATE December 5, 1975

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: