DISTRIBUTION SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION FILE U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name OTHER-		-	
NEW MEXICO OIL CONSERVATION COMMISSION FILE U.S.O.5.5. Substance of Lorente Substance of Lo	NC. OF COPIES RECEIVED		Form C-103 Supersedes Old
Section Sect			
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THAT PLANT OF HEALTH OF HEA			Effective 1-1-65
LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THAT PROVIDED TO SERVING THE PROPERTY OF THE PROPERTY O		- mr. 12 3 37 P	5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS ON OF HER THIS PROBLEM TO THE			State Fee.
ORL DE OFFICE OF THE STAND CLEMENT STAND CANNON PLUE AND ARANDON PLUE OF ALTERING CASING PROPERTY SEE RULL E 1703. 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed and pump. Cleared well in. Mill run OOR test and place well on production at a later date. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY CRESCHER PROPERTY AREA OF SIGNED OR SI	OPERATOR		5, State Oil & Gas Lease No.
ORL DE OFFICE OF THE STAND CLEMENT STAND CANNON PLUE AND ARANDON PLUE OF ALTERING CASING PROPERTY SEE RULL E 1703. 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed and pump. Cleared well in. Mill run OOR test and place well on production at a later date. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY CRESCHER PROPERTY AREA OF SIGNED OR SI			
Only Oll Corporation 1. Address of Operation 2. Address of Operation 3. Address of Operation 4. Address of Operation 5. Address of Operation 6. Address of Operation		DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
Gulf Oil Corporation A Addition of Operation Bus 670, Nobbs, New Mexico L, Location of Well ONIT LETTER B 660 TEST FROM THE LINE, SECTION 5 TOWNSHIP 22-8 RANGE 37-E NUMBER 15. Elevation (Show whether DF, RT, GR, etc.) 3159' DF Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK TEMPORARRIEV ARANDON PULL OR ALTER CASING OTHER OT	OIL GAS	OTHER-	7. Unit Agreement Name South Penrose Skelly Uni
The conting of Well B Check for the conting of Well Unit Letter B C	2. Name of Operator		8. Farm or Lease Name
L. Coston of Well UNIT LETTER B. 660 FETT FROM THE TIME LINE, SECTION 5 TOWNSHIP 22-8 RAMSE 37-B TOWNSHIP 12, COUNTY 12, COUNT		1	
THE B 660 THE B 660 TOWNSHIP 22-8 THE BST LINE, SECTION 5 THE BST LINE,	· _	Mond on	
Perform Skelly THE Bast LINE, SECTION 5 TOWNSHIP 22-8 RANGE 37-E NAME. 15, Elevation (Show whether DF, RT, GR, esc.) 3459* DF Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PREFORM REMEDIAL WORK COMMENCE ORIGING OF HIS AND ABANDON CHANGE PLANS COMMENCE ORIGING OF HIS ADDRESS OF HIS ADDRE		MEXICO	
THE LIME, SECTION 5 TOWNSHIP 22-8 BASE 37-E MAPPAL 15. Elevation (Show whether DR, RT, GR, etc.) 31.59' IB Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PULL DRIALTER CASING CHANGE PLANS Thereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY C. D. BORLAND ANALLY ARRESTS ANALLY ARRESTS 10. Thereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY C. D. BORLAND ANALLY ARRESTS ANALLY ARRESTS 10. Thereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY C. D. BORLAND ANALLY ARRESTS ANALL 10. 106.7	R	660 Nerth 1980	Permana Skelly
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PULL OR ALTER CASING OTHER TO ABOUT TEST AND CEMENT 198 OTHER OTHER TO ABOUT TEST AND CEMENT 198 OTHER TO THER	UNIT LETTER	FEET FROM THE LINE AND F	EET FROM
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PULL OR ALTER CASING OTHER TO ABOUT TEST AND CEMENT 198 OTHER OTHER TO ABOUT TEST AND CEMENT 198 OTHER TO THER	Inst Ins sec	5 TOWNSHIP 22-8 37-E	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK TEMPORATILY ABANDON CHANGE PLANS CHANGE PLANS	THE LINE, SEC	TION HANGE	— MPM.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK TEMPORARILY ABANDON PILLO AN ALTER CASING OTHER OTHER OTHER TO AND ALTER CASING OTHER TO AND ALTER CASING OTHER OTHER TO AND ALTER CASING OTHER TO AND ALTER CASING OTHER OTHER TO AND ALTER CASING OTHER TO AND ALTER CASING OTHER OTHER TO AND ALTER CASING OTHER TO AND CEMENT JOB OTHER TO AND CEMENT JOB OTHER TO AND CEMENT JOB OTHER TO AND ALTER CASING PLUG AND ABANDONMENT CAMBER COMMENCE OFILLING OPNS. CAMBER COMMENCE OFILLING O			12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPO		3459' 111'	Let
TEMPORABILITY ABANDON PULL OR ALTER CASING CHANGE PLANS	Check		
Temporarily abandon Pull or alter casing Other Change Plans Other Cleaned out 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see Rule 1703. 3759' TD. Pulled tubing, rods and pump. Cleaned out from 3739' to 3752' with 3½ SP. Ran 3702' of 2-3/8° tubing with pin collar on bottom, set at 3716', SN at 3682'. Ran rods and pump. Closed well in. Will run GOR test and place well on production at a later date. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY C. D. BORLAND. Area Production Managery Area Product			
OTHER OT	PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
Cleared out 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see Rule 1703. 3759' TD. Pulled tubing, rods and pump. Cleaned out from 3739' to 3752' with 32" SP. Ran 3702' of 2-3/8" tubing with pin collar on bottom, set at 3716', SN at 3682'. Ran rods and pump. Closed well in. Will run GOR test and place well on production at a later date. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY C. D. BORLAND. Areal Production Managery. Areal 20, 1967.	=	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SER RULE 1703. 3759' TD. Pulled tubing, rods and pump. Cleaned out from 3739' to 3752' with 32" SP. Ran 3702' of 2-3/8" tubing with pin collar on bottom, set at 3716', SN at 3682'. Ran rods and pump. Closed well in. Will run OOR test and place well on production at a later date. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY C. D. BORLAND. Appell 10 1067	PULL OR ALTER CASING	-	
Thereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY C. D. BORLAND. Original Signed BY C. D. BORLAND. OCCUPANTIAN STATE AND STATE A		OTHER	
3759' TD. Pulled tubing, rods and pump. Cleaned out from 3739' to 3752' with 32" SP. Ran 3702' of 2-3/8" tubing with pin collar on bottom, set at 3716', SN at 3682'. Ran rods and pump. Closed well in. Will run GOR test and place well on production at a later date. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY C. D. BORLAND. Areal 10. 1067	OTHER	Cleaned out	
ORIGINAL SIGNED BY C. D. BORLAND Area Production Manager Area 1 10 1067	3702' of 2-3/8" tubi and pump. Closed we	ing with pin collar on bottom, set at 3716', all in. Will run GOR test and place well on	SN at 3682*. Ran rods production at a later
	ORIGINAL SIGNED BY	on above is true and complete to the best of my knowledge and belief.	
		<u> </u>	

CONDITIONS OF APPROVAL, IF ANY: