NO. OF COPIES RECEIVED		
DISTRIBUTION	7	Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE		Effective 1-1-65
U.S.G.S.	-	
		5a. Indicate Type of Lease
OPERATOR	_	State Fee
OPERATOR		5, State Oil & Gas Lease No.
SUND	RY NOTICES AND REPORTS ON WELLS	
	RY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	
	C TOTY FOR SUCH PROPOSALS.)	7. Unit Agreement Name
WELL WELL	OTHER- Dual Completion - Blinebry - Drinkard	V. Chit Adreement Hume
2. Name of Operator		8. Farm or Lease Name
Gulf Oil Corporation	1	Lee Stebbins (NCT-A)
3, Address of Operator		9. Well No.
Box 670, Hobbs, N.M.	3	
4. Location of Well		
F	1870 north 2000	10. Field and Pool, or Wildcat
	1870 FEET FROM THE north LINE AND 2092 FEET PRO	Drinkard
THE West	5 000 000	
THE LINE, SECTI	ION 5 TOWNSHIP 225 RANGE 37E NMPH	· ////////////////////////////////////
	15. Elevation (Show whether DF, RT, GR, etc.)	
		12. County
16.	3451 ° GL	
Check	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
		T REPORT OF:
r		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER Dualled Drinkard	i with existing
OTHER	Blinebry MC -21	87
		~1

65951 TD.

Pulled producing equipment. Ran tubing and packer and set packer at 5625. Pressured casing to 1000#, OK. Pumped 150 sacks Class C cement and 100 sacks Class C Neat. Displaced cement below packer. Obtained 1000# squeeze on Blinebry perforations 5705-5856 with 225 sacks in formation and 25 sacks in casing. WOC 12 hours. Drilled cement 5640-5862*. Tested squeezed Blinebry perforations 5705-5856' with 1000# 30 minutes, OK. Drilled out cement and CIBP at 6030' and pushed to 6317'. Set packer at 6312'. Loaded tubing-casing annulus; pressure tested BP and tubing with 2000#, OK. Set packer at 5966'; pressured tubing-casing annulus to 1000#, OK. Mixed and pumped 125 sacks Class C cement and 50 sacks Class C Neat. Displaced cement 60' below packer. Squeezed Tubb perforations 6090-6295' to 1500# with 170 sacks in formation and 5 sacks in casing. WOC 12 hours. Pressured Tubb Gas perforations 6090-6295" with 500#, held OK. Drilled out cement and cleaned out to 6595". Ran tubing and packer, spotted 100 gallons 15% NEHCL acid on open hole section 6595-6532", set packer at 6342". Frac treated in 3 stages using 6000 gals gel water and 15,000 gallons containing 1-2# SPG. Maximum pressure 4250#, minimum 3300#. AIR 15 bpm. ISIP 1600#, after 2 hours 800#. Spotted 29 sacks 8-12 sand to obtain temporary PB to 65271. Spotted 200 galbns 15% NEA over Drinkard casing perforations 6510-63401. Reset packer at 6342*. Fraced Drinkard perforations 6430-6510* in 4 equal stages using 8000 gallons gel water and 20,000 gallons containing 1-2# SPG. Flushed with 40 bbls gel water. IR 15 bpm at 4900#. Maximum pressure 4950#, minimum 4200#. ISIP 2000#, after 15 minutes 1150#. (continued)

18. I hereby certify		omplete to the best of my knowledge and belief.	······································
IGNED	Hanking	Area Engineer	DATE 7-23-75
	John Bargen	Gogløgist	JUL 24 TREE
PPROVED BY	PPROVAL, IF ANY:	TITLE	DATE