STATE UP NEW MEXICU ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	
SANTA PE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPPRATOR	

L CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 2088 SANTA FE, NEW MEXICO 87501		Form C-103 Revised 10-1-78
FILE U.S.G.S.		- W M - 2010	5a, Indicate Type of Lease
LAND OFFICE			State State Oti & Gas Lease No.
			- mannen
IDO HOT URE THIS FORM FOR PRO	Y NOTICES AND REPORTS (POSALS TO PHILL ON TO SEEPEN OF PLI ON FOR PERMIT - " (FORM C-101) FOR	UG BACK TO A DIFFERENT RESERVOIR.	
OIL GAB WELL	QTHER-		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporat	ion		H. T. Mattern (NCT-D)
P. O. Box 670, Ho	nhhs NM 88240		9. Well No.
4. Location of Well	7550, 141 00240		10. Field and Pool, or Wildcat
UNIT LETTER D	660 PEET FROM THE NOT	th LINE AND 660 PEET FE	Eumont Gas
THE West LINE, SECTION	6 TOWNSHIP	22S RANGE 37E NM	PM.
	15. Elevation (Show when		12. County
16. Check	· · · · · · · · · · · · · · · · · · ·	6 GL e Nature of Notice, Report or	Lea ////////////////////////////////////
	ITENTION TO:		ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPMS. CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT X
PULL OR ALTER CABING	CHANGE PLANS	OTHER	
07HEA	[
17. Describe Proposed or Completed Opwork) SEE RULE 1603.	erations (Clearly state all pertinent	details, and give pertinent dates, includ	ling estimated date of starting any proposed
with open-ended t 1270'-1170'. Cir 150' cement to 30	cubing to 2900'. Circulate cement 950'-300'00' from surface. Spond clear location. OC	at 2940', dump 35 sacks (ulate abandonment mud. So'. Tag cement at 450', t 35' cement to surface. D representative visited	Spot 100' cement plug test 500#. Circulate Erect dry hole
	•		
18.1 hereby certify that the information	shave is true and complete to the hi	set of my knowledge and belief	
PPt	TITLE	Area Engineer	PATE4-19-82
801 11	So.	OIL & GAS INSPECT	
APPROVED BY	YITLE_		7009

APR 19 1982