

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM-1410
2. NAME OF OPERATOR Meridian Oil Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 51810, Midland, TX 79710-1810	3a. AREA CODE & PHONE NO. 915-686-5767	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface M, 330' FSL & 610' FWL		8. FARM OR LEASE NAME Elliott B-6
		9. WELL NO. 1
		10. FIELD AND POOL, OR WILDCAT Eumont (Yates-7Rvrs-Qn)
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 6, T-22-S, R-37-E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3457' GR	12. COUNTY OR PARISH Lea
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input checked="" type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input checked="" type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other) Convert Dual Well to Single Prod.	<input type="checkbox"/>		<input type="checkbox"/>

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well is presently a dual well. Propose to shut off the Arrowhead-Grayburg Oil Pool by setting a CIBP @3660' and only produce the Eumont (Yates-7Rvrs-Queen) Gas Pool. Add Penrose perforations, acidize and fracture.

Run GR/CCL for correlation. Perforate Penrose with 2 SPF at 3563'-33587' (50 shots). Set CIBP at 3660'. Breakdown perfs with 1500 gls 2% KCl wtr w/75 7/8" RCNBS. Test annulus to 500 psi. Fracture stimulate Penrose with 17,300 gallons of 50-Quality CO2 foam and 71,000 lbs of 12/20 mesh Brady sand. Clean out with foam to PBD. Put on production.

RECEIVED
JUL 19 10 23 AM '91
CARTER AREA

18. I hereby certify that the foregoing is true and correct

SIGNED	<u>Maria L. Perez</u>	TITLE	<u>Production Asst.</u>	DATE	<u>7-17-91</u>
(This space for Federal or State office use)					
APPROVED BY	<u>David R. Glass</u>	TITLE	<u></u>	DATE	<u>8-5-91</u>
CONDITIONS OF APPROVAL, IF ANY:					

*See Instructions on Reverse Side