

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		API NO. (assigned by OCD on New Wells) <b>30-025-10094</b>
		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		6. State Oil & Gas Lease No. <b>N/A</b>
2. Name of Operator <b>CHEVRON U.S.A. PRODUCTION CO.</b>		7. Lease Name or Unit Agreement Name <b>ARROWHEAD GRAYBURG UNIT</b>
3. Address of Operator <b>P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS</b>		8. Well No. <b>184</b>
4. Well Location Unit Letter <b>D</b> : <b>660</b> Feet From Th <b>NORTH</b> Line and <b>660</b> Feet From The <b>WEST</b> Line Section <b>7</b> Township <b>22S</b> Range <b>37E</b> NMPM <b>LEA</b> County		9. Pool name or Wildcat <b>ARROWHEAD/GB</b>
10. Elevation(Show whether DF, RKB, RT, GR, etc.) <b>3460 GE</b>		

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTER CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐  
CASING TEST AND CMT JOB ☐  
OTHER: **DPN, PERF, STIM.** ☒

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including  
estimated date of starting any proposed work) SEE RULE 1103.

MIRU, POOH WITH PRODUCTION EQUIP.  
DRILL NEW FORMATION FROM 3755-3868.  
LOG HOLE: SDL-DSN-GR-CAL-CCL.  
ACIDIZE OPEN HOLE WITH 1500 GALS. OF 15% NEFE. SWAB TEST HOLE.  
PERF 3648-3624 WITH 4" GUNS, 2 JHPF, 80 DEG PHSD.  
ACDZ PERFS WITH 500 GALS OF 15% NEFE. SWAB TEST.  
TIH WITH TBG. AND RODS. RETURN TO PRODUCTION ON 4-14-92

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE **TECH. ASSISTANT** DATE: **4-28-92**

TYPE OR PRINT NAME **P.R. MATTHEWS** TELEPHONE NO. **(915)687-7812**

APPROVED BY JERRY SEXTON DATE **APR 30 '92**

CONDITIONS OF APPROVAL, IF ANY: