

OIL CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☐ Fee ☒
3. State Oil & Gas Lease No.

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670, Hobbs, NM 88240

Location of Well

UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 7 TOWNSHIP 22S RANGE 37E WMPM.

7. Unit Agreement Name

8. Farm or Lease Name

H. T. Mattern (NCT-D)

9. Well No.

4

10. Field and Pool, or Wildcat

Arrowhead Grayburg

15. Elevation (Show whether DF, RT, GR, etc.)

3460

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

REFORM REMEDIAL WORK ☐
IMPROVEMENT ABANDON ☐
LL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER add perms, acidz ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Work performed 1-2-88 through 1-7-88

TD: 3755 PB: 3755

POOH w/ production equipment, break circulation w/ air, cleanout soft fill, drill hydromite plug to 3755. circ 25 bbl CBW, log with GR/CNS/CCL, Perf OH w/30 shots using 2 JHPF at 3681,3686,3691,3696,3702,3707,3712,3717,3722,3727,3742,3752, perf bottom 9 zones on 1st run, perf top 6 zones on run #2. break circulation w/ CFM air cleanout to 3760 WL, wash to 3720, drill to 3726, wash to 3748, drill to TD. Blow wellbore clean. Set pkr at 3589, load tbg w/CBW and test to 2500psi, ok. Load and test annulus w/53.8 bbl CBW to 500psi, acidize w/2700 gallons 15% NEFE HCL, swab, RIH on Prod. tbg, tagg up on fill at 3661, cleanout fill from 3742-3755, tag at 3755, GIH w/ 2 3/8" 4.7#, J-55, 8rd EUE, tbg SN at 3716, EOT at 3731. NDBOPE land tbg, NU pmp tee, Run rods, prod. pmp, space out, hang well, RD MO PU. Turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Akim

TITLE Staff Drilling Engineer

DATE January 11, 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

COPIES OF APPROVAL, IF ANY:

TITLE

DATE

JAN 14 1988

RECEIVED

JUN 19 1988

CCD
HOBBS OFFICE