

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		API NO. (assigned by OCD on New Wells) <b>30-025-10096</b>	
		6. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WATER INJ <input type="checkbox"/>		6. State Oil & Gas Lease No. N/A	
2. Name of Operator <b>CHEVRON U.S.A. INC.</b>		7. Lease Name or Unit Agreement Name <b>ARROWHEAD GRAYBURG UNIT</b>	
3. Address of Operator <b>P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE</b>		8. Well No. <b>214</b>	
4. Well Location Unit Letter <b>O</b> : <b>660</b> Feet From The <b>SOUTH</b> Line and <b>1980</b> Feet From The <b>EAST</b> Line Section <b>7</b> Township <b>22 SOUTH</b> Range <b>37E</b> NMPM <b>LEA</b> County		8. Pool name or Wildcat <b>ARROWHEAD/GB</b>	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) <b>3426' GL</b>			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <b>DEEPEN, ADD PERFS &amp; ACDZ</b> <input checked="" type="checkbox"/>	
		<b>CONVERT TO INJ</b>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK STARTED 2/23/94. MIRU PU, ND WH, NU BOP. TAG CMT @3710'. DRILL TO 3828'.  
RUN GR/CCL/SPECTRAL LITHODENSITY/CALIPER LOG. GIH W/FLOAT SHOE AT 3832'.  
DISPLACE HOLE W/FW, MIX & PUMP 150 SX CL H W/2#/SX CAL-SEAL. POOH W/TBG.  
TAG CMT @2710'. DRILL TO 3832'. PERF 2824'-3656' W/2 JHPF.  
ACDZ PERFS W/2 BBLs ACID PER SET OF PERFS. SET PKR @3592'. ND BOP, NU WH.  
RD PU, TURN OVER TO PRODUCTION 03/09/94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wendi Kingston TITLE TECH. ASSISTANT DATE: 03/29/94  
TYPE OR PRINT NAME WENDI KINGSTON TELEPHONE NO. (915)687-7436

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY Jerry Sexton TITLE DISTRICT I SUPERVISOR DATE MAR 31 1994  
CONDITIONS OF APPROVAL, IF ANY: